Project - Quarterly Progress Report

Promoter's Name	:	BBCL WESTERN CONSTRUCTION
Project Name	:	BBCL VILLA HAVEN Phase IV
Project Registration No	:	TN/02/BUILDING/0197/2019
Quarter Ending	:	June 2023

A. Sales

SI.	Description	Cumulative No.	Total Area
No.		of Units upto the	
		Quarter	
1.	Plots/Flats Booked size wise (As	34	
	given in Carpet Area Statement		
	while registering)		
2.	Parking Lots	34	
3.	UDS Registered in Sq.m.		482.04

B. Construction

SI.	Description	Block/Tower No.	Status
No.			
1.	Stage of construction of each	Enclosed S	eparately
	Block/Tower, Floor wise		
2.	Status of common Amenities for	us of common Amenities for Enclosed Separately	
	each Block/Tower, Item wise		

Sl.No.	Description	Percentage
1.	Percentage of Completion	
	i) Physical	77
	ii) Financial (Enter Anticipated Project Cost in Lakhs)	77

C. Details of Clearances

- 1. Completion Certificate No. ----- (only CC No. in Text Format)
- 2. Compliance Report, if any (Kindly Specify) ----- (in PDF Format)
- 3. Annual Audit Report of Special Account in Form 7 ----- (in PDF Format)

D. Latest Photo with Date (Atleast from 2 angles) ----- (in PDF Format) - Enclosed

S No	Villa No	Construction Status
1	44	Internal and external plaster completed, water proofing completed
2	45	Internal and external plaster completed, water proofing completed
3	51	Final roof completed, Gf block work in prg
4	52	Final roof completed, Gf block work in prg
5	58	100 % completed
6	59	100 % completed
7	65	100 % completed
8	66	100 % completed
9	72	100 % completed
10	73	Flooring completed, internal painting in prg
11	79	100% completed
12	80	100% completed
13	86	Flooring in prg
14	87	Block work completed, External plaster in progress
15	93	100% completed
16	94	100% completed
17	101	100% completed



S No	Villa No	Construction Status
18	102	100% completed
19	103	Plastering completed. Water proof and terrace tiling completed
20	104	Plastering in progress
21	105	100% completed
22	106	Completed till plastering, water proof and terrace tiling completed
23	109	Internal and external plaster completed, water proofing completed
24	110	95% Completed
25	111	95% Completed
26	112	Plastering completed
27	113	Plastering completed
28	114	100% completed
29	115	Yet to start
30	117	100 % completed
31	118	100 % completed
32	119	100 % completed
33	122	Wiring completed, internal painting in prg
34	123	100 % completed



Villa 114 – 100% work completed





Villa 94 – 100% work completed





Villa 119 – 100% work completed





Villa 103 – Plastering Work, Water proofing and terrace tiling work completed





Villa 112 & 113 - Plastering work completed





Villa 104 - Internal Plastering & External Plastering is on progress





Villa 105 – 100% Completed



