\* M.: +91-9819882662 \* TEL: 022-24374185



## **ARCHITECTS & ENGINEERS**

- 15/2, Jeelani Manzil, Opp. Portuguese Church, Gokhale Road (N), Dadar (W), Mumbai - 400 028.
- E-mail: vinnidesai1@gmail.com

## FORM = 1 ARCHITECT'S CERTIFICATE

Date: 13th July 2021.

To,
MACROTECH DEVELOPERS LIMITED

Subject: Certificate of Percentage of Completion of Construction Work of 1 No. of Buildings of the Project "LODHA PAREL PROJECT" situated on the Plot bearing C.N. No. / CTS No. / Survey no./ Final Plot No. 137/74 demarcated by its boundaries (latitude and longitude of the end points) Dadabhai Chamarbaugwala Road to the North Ai Mai Merwanji Street to the South E Borges Road to the East Narayan Meghaji Institute of Labour Studies Bldg to the West of Division Konkan Village Mumbai City & Mumbai City Taluka Mumbai City District PIN 400012 admeasuring 4,299 sq.mts. area being developed by MACROTECH DEVELOPERS LIMITED

Sir,

We have undertaken assignment as Architect /Licensed Surveyor of certifying Percentage of Completion of Construction Work of the 1 Buildings of LODHA PAREL PROJECT project, situated on the plot bearing C.N. No/CTS No. /Survey no. / Final Plot no. 137/74 of Division Konkan Village Mumbai City & Mumbai City Taluka Mumbai City District PIN 400012 admeasuring 4,299 sq.mts. area being developed by MACROTECH DEVELOPERS LIMITED

Following technical professionals are appointed by Owner / Promoter :-

- (i) Pradeep Kamble & Associates as L.S. / Architect;
- (ii) Kapadia Associates Pvt. Ltd. as Structural Consultant
- (iii) AECOM as MEP Consultant
- (iv) Mr. Vaibhav Bhave as Site Head

Based on site inspection, with respect to each of the Building of the aforesaid project, we certify that as on 30<sup>th</sup> June 2021, the percentage of work done for each of the building of "LODHA PAREL PROJECT" is as per Table A herein below. The percentage of the work executed with respect to each of the activity of the entire phase in Table B.

## TABLE-A

## Parel Project - Tower C

Sr. No.	Tasks / Activity	Percentage of work done
1	Excavation	100%
2	1number of Basements (S) and Plinth	100%
3	7 number of podiums	100%
4	1Stilt Floor	NA
5	35number of Slabs of Super Structure	90%
6	Internal walls, Internal Plaster, Floorings within Flats/Premises, Doors and Windows to each of the Flat/Premises	16%
7	Sanitary Fittings within the Flat/Premises, Electrical Fittings within the Flat/Premises	0%
8	Staircases, Lifts Wells and Lobbies at each Floor level connecting Staircases and Lifts, Overhead and Underground Water Tanks	45%
9	The external plumbing and external plaster, elevation, completion of terraces with waterproofing of the Building/Wing,	0%
10	Installation of lifts, water pumps, Fire Fighting Fittings and Equipment as per CFO NOC, Electrical fittings to Common Areas, electro, mechanical equipment, Compliance to conditions of environment /CRZ NOC, Finishing to entrance lobby/s, plinth protection, paving of areas	1%
	appurtenant to Building/Wing, Compound Wall and all other requirements as may be required to Obtain Occupation / Completion Certificate	

Table B - Common Areas & Amenities (Project level)

Sr. No.	Common areas and Facilities, Amenities	Percentage of Work done
1	Internal Roads &Foothpath	0%
2	Water Supply	5%
3	Sewarage (Chamber, lines, Septic Tank, STP)	0%
4	Storm Water Drains	0%
5	Landscaping & Tree Planting	0%
6	Street Lighting	0%
7	Community Buildings	0%
8	Treatment and disposal of sewage and sullage water	0%
9	Solid Waste management & disposal	0%
10	Water conservation, Rain water	0%
11	Energy management	0%
12	Fire protection and fire safety requirements	5%
13	Electrical meter room, sub-station receiving station	0%
14	Aggregate area of recreational Open Space	0%
15	Open Parking	0%
16	Closed Parking	0%
17	Others (Option to Add more)	

Yours Faithfully,

For Vilas Desai & Associates

Architect: Vini Vilas Desai Registration No:CA/2008/43203