p. n. bhobe & associates

architects and interior designers
223/a, ramesh ghar,
t. h. kataria marg,
mahim, mumbai 400 016.
tel. no. 24378695.

Date: 25th July 2017.

FORM 1

To,
M/s Kumar Matunga Project LLP
A/1, Rajkamal Apartment,
Raj Kamal Lane, Parel,
Mumbai - 400 012.

Subject:

Certificate of Percentage of Completion of Construction Work of a standalone building [MahaRERA Registration Number being applied] on the Plot bearing C.S. No. 297/10 of Matunga Division, demarcated by its boundaries (LATITUDE -19.028857–LONGITUDE - 72.853109) to the North, (LATITUDE - 19.028695- LONGITUDE - 72.85319) to the South; (LATITUDE - 19.028799 – LONGITUDE - 72.853238) to the East; (LATITUDE - 19.028727 – LONGITUDE - 72.853046) to the West; situated at Telang Road, Matunga, Mumbai- 400 019 admeasuring 571.07 sq.mts being developed by M/s Kumar Matunga Project LLP.

Ref

File at E.E.(B.P.) City's office bearing no. CHE/CTY/1326/F/N/337.

Sir,

We, M/s P.N Bhobe & Associates, have undertaken assignment as the Architects for certifying Percentage of Completion of Construction Work of "Co-operative house", a standalone building [MahaRERA Registration Number-being applied] situated on plot bearing C. S. No. 297/10 of Matunga Division, situated at Telang Road, Matunga, Mumbai 400 019 demarcated by its boundaries admeasuring 571.07 sq.mts. being developed by M/s Kumar Matunga Project LLP.

Following technical professionals are appointed by the Owner / Promoter:—

- (i) M/s. P. N. Bhobe and Associates as the Architects.
- (ii) M/s Achyut Watre of J₊W as Structural Consultants.
- (iii) MEP Consultant M/s Urja Building Services Consultants Pvt. Ltd.
- (iv) Mr. Apurva Shah as Site Supervisor.

the ..

Contd...2

Based on the Site Inspection, with respect to the standalone Building of the aforesaid Real Estate Project, I certify that as on the date of this certificate, the Percentage of Work done for the building of the registration being applied under MahaRERA is as per "Table A" herein below. The percentage of the work executed with respect to each of the activity of the entire phase is detailed in "Table B".

TABLE-A

Sr.	Tasks / Activity	Percentage
No.		of work done
(1)	(2)	(3)
1	Excavation	100%
2	Number of Basement(s) and Plinth	100%
3	Number of Podiums	Nil
4	Stilt Floor	Nil
5	Slabs of Super Structure	Nil
6	Internal Walls, Internal Plaster, Floorings within Flats/Premises,	Nil
	Doors and Windows to each of the Flat/Premises.	
7	Sanitary Fittings within the Flat/Premises, Electrical Fittings within	Nil
	the Flat/Premises.	
8	Staircases, Lifts Wells and Lobbies at each Floor level connecting	15%
	Staircases and Lifts, Overhead and Underground Water Tanks.	
9	The external plumbing and external plaster, elevation, completion of	Nil
	terraces with waterproofing of the Building/Wing.	
10	Installation of lifts, water pumps, Fire Fighting Fittings and	Nil
	Equipment as per CFO NOC, Electrical fittings to Common Areas,	
	electro, mechanical equipment, Compliance to conditions of	
	environment /CRZ NOC, Finishing to entrance lobby/s, plinth	
	protection, paving of areas appurtenant to Building/Wing,	
	Compound Wall and all other requirements as may be required to	
	obtain Occupation / Completion Certificate.	



TABLE-B
Internal and External Development Works.

Sr.	Common areas and Facilities, Amenities	Proposed (Yes/No)	Percentage of Work done	Details
	(2)	(3)	(4)	(5)
(1)	Internal Roads & Foothpaths.	NO	N.A.	
1		YES	Nil	
3	Water Supply Sewarage (chamber, lines, Septic Tank, STP).	YES	Nil	
4	Storm Water Drains	YES	Nil	
5	Landscaping & Tree Planting	NO	N.A.	
	Street Lighting	NO	N.A.	
6	Community Buildings	NO	N.A.	
8	Treatment and disposal of sewage and sullage water	NO	N.A.	
9	Solid Waste management & Disposal	NO	N.A.	
10	Water conservation, Rain water harvesting	NO	N.A.	
11	Energy management	NO	N.A.	
	Fire protection and fire safety requirements	YES	Nil	
12	- sub station receiving	YES	Nil	
14	(O ii t Add more)	, NO	N.A.	

Thanking you,

M/s P. N. Bhobe & Associates

(Mr. P. N. Bhobe) (Reg. No.CA/80/5997)