DesignSpace

Architects & Interior Designers



ARCHITECT'S CERTIFICATE (F1)

Date:03-08-2022

To

The Omsree Builders and Developers LLP, H No:5-8-40, Rainbow Farm, Beside Valerian Grammar School, Yapral, Secunderabad – 87.

Subject: Certificate of Percentage of Completion of Construction Work of272Flats of the 'OMSREE SKYPARK'Projectsituated on the land bearing Survey no.survey Nos. Survey No. 117/P & 118/P demarcated by its boundaries17°32'03.1"to the North78°28'39.4"to the East of Kompally Village, Gandimaisamma Mandal, Medchal District., Telangana admeasuring 16187.45sq.mts.area beingdeveloped by Omsree Builders and DevelopersLLP

Sir.

We**Design Space Architects & Interior Designers** have undertaken assignment as Architect of certifying percentage of Completion of Construction Work of the **Flats** of the **"OMSREESKY PARK"** the Project, situated on the plot bearing **117/P & 118/P**, Kompally Village, Gandimaisamma Mandal, Medchal District., Telangana PIN: 500100 admeasuring **16187.45** sq.mts.. area being developed by Omsree Builders and Developers LLP

- 1. Following technical professionals are appointed by Owner / Promoter: -
- (i) Shri Murali Krishna as Architect
- (ii) Shri Kasi Viswanath. S as Structural Consultant
- (iii) ShriSrinivas Vallurias MEP Consultant
- (iv) Shri MohdMinhajuddinas Site Engineer

Based on Site Inspection, with respect to each Flatof the foresaid Real Estate Project,

I certify that as on the date of this certificate, the percentage of work done for each of thebuilding/Wing of the Real Estate Project as registered vide number _____ under TSRERA is as per table A herein below. The percentage of the work executed with respect to each of theactivity of the entire phase is detailed in Table B.

Table A

STATUS OF WORK COMPLETION IN "OMSREE SKY PARK"

		- 2
RI	ock	1
ы	ULI	_

Excavation In Progress

Stilt 1

1.No Progress

Stilt 2

1.No Progress

Stilt 3

1.No Progress

Stilt 4

1.No Progress

First Floor

1.No Progress

Second Floor

1.No Progress

Third Floor

1.No Progress

Fourth Floor

1.No Progress



Fifth Floor

1.No Progress

Sixth Floor

1.No Progress

Seventh Floor

1.No Progress

Eighth Floor

1.No Progress

Ninth Floor

1.No Progress

TenthFloor

1.No Progress

TABLE-B

Internal & External Development Works in Respect of the entire Registered Phase

S.No	Common areas and Facilities, Amenities	Proposed (Yes/No)	Percentage of Work done	Details
1	Internal Roads & Foot paths	Yes	0	The Works are yet to get started
2	Water Supply	Yes	0	The Works are yet to get started

Mull (CA)2000/25762

3	Sewerage (chamber, lines, Septic Tank,	Yes	0	The Works are yet to get started
	STP)			Started
4	Storm Water	Yes	0	The Works are
	Drains			yet to get
	4			started
 5	Landscaping &	Yes	0	The Works are
	Tree Planting	100		yet to get
	11001111111			started
5	Street Lighting	Yes	0	The Works are
<i>3</i>	btreet highting	103	ľ	yet to get
				started
7	Community	Yes	0	The Works are
,	Buildings	165	0	
	Dunungs			yet to get started
8	Treatment and	Yes	0	The Works are
5	disposal of	res	0 7	
	sewage and			yet to get
	sullage water			started
	Sullage Water			
)	SolidWaste	No	0	NA
	management &	\$100 St Steel		
	Disposal			
10	Water	Yes	0	The Works are
	conservation,			yet to get
	Rain water			started
	Harvesting			
11	Energy	Yes	0	The Works are
	Management	•		yet to get
				started
12	Fire protection	Yes	0	Applicable in
	and fire safety			Common Areas
	requirements			and Parking
				Areas
13	Electrical meter	Yes	0	The Works are
	room, sub-			yet to get
	station,			started
	receiving station		×	
14	External	Yes	0	Not Yet Started
	Compound Wall			
	and Main Gate			(N)



For Design Space Architects & Interior Designer

Murali Krishna