

G-7, 8, 'D' Wing, Sethi Palace, Ambadi Road, Vasai Road (W), Dist. Palghar - 401 202.

Tel. : 0250-2336318 / 2333404 E-mail : encon4@gmail.com

encon1@rediffmail.com

VP-5299/RR-A/01

Date: -29-07-2022

## Annexure A Form 1 [see Regulation] ARCHITECT'S /ENGINEER'S CERTIFICATE

To,
Mr. Moreshwar K. Baria,
I / 004/005, Laxman Apartment,
Ayodhya Nagar,
Bariwada Road Agashi,
Virar (W),
Taluka Vasai, Dist:- Palghar.

Subject: - Certificate of Percentage of Completion of Construction Work of "DAULAT IMPERIA" of Building No.2 (St. + 14 Floors) [as per approved plan] having MahaRERA Registration No. P99000006055 being developed by KAPCON VENTURES. [VVCMC File No.2088-VP-5299].

Sir.

I, Mr. Sanjay S. Narang have undertaken assignment as Licensed Engineer of certifying Percentage of Completion of Construction Work of "DAULAT IMPERIA" of Building No.2 (St. + 14 Floors) [as per approved plan] having MahaRERA Registration No. P99000006055 being developed by KAPCON VENTURES. [VVCMC File No.2088-VP-5299].

Based on Site Inspection, with respect to Layout/each of the Building/Wing of the aforesaid Real Estate Project, I certify that as on the date of this certificate, the Percentage of work done for each of the building/Wing of the Real Estate Project as registered vide number under MahaRERA is as per table A herein below. The percentage of the work executed with respect to each of the activity of the entire phase is detailed in Table B.

North



G-7, 8, 'D' Wing, Sethi Palace, Ambadi Road, Vasai Road (W), Dist. Palghar - 401 202.

	TABLE - A			
Sr. No.	Tasks/Activity	Percentage Of Work  Done		
1.	Excavation	100%		
2.	Basement	N.A.		
3.	Plinth	100%		
4.	Stilt Floor	100%		
5.	Podiums	N.A.		
6.	15 number of slabs of Super Structure	100%		
7.	Internal walls, internal plaster, floorings within flats/premises. Doors and windows to each of the flat/premises	65%		
8.	Sanitary fittings within the flat/premises, electrical fittings within the flat/premises.	10%		
9.	Staircases, lift wells and lobbies at each floor level connecting staircases and lifts overhead and underground water tanks.	90%		
10.	The external plumbing and external plaster, elevation, completion of terraces with water proofing of the building/wings.	50%		
11.	Installation of lifts, water pumps, firefighting and equipment as per CFO NOC, electrical fittings to common areas, electro, mechanical equipment, compliance to condition of environment/CRZ NOC, finishing to entrance lobby/s, Plinth protection, paving of areas appurtenant to building/wings, compound wall and all other requirements as may be required to obtain completion certificate.	0%		





G-7, 8, 'D' Wing, Sethi Palace, Ambadi Road, Vasai Road (W), Dist. Palghar - 401 202.

Tel. : 0250-2336318 / 2333404 E-mail : encon4@gmail.com

encon1@rediffmail.com

	TABLE – B						
Sr. No.	Common areas and facilities, amenities	Proposed (Yes/No)	Percentage of work done	Details			
1,	Internal roads & footpaths	Yes	50%	•			
2.	Water supply	Yes	50%	-			
3.	Sewerage (Chamber, lines, septic tank, STP)	Yes	0%	•			
4.	Storm water drains	Yes	20%	•			
5.	Landscaping & tree planting	Yes	0%	•			
6.	Street Lighting	Yes	20%	•			
7.	Community buildings	No	N.A.	•			
8.	Treatment and disposal of sewage and sullage water	Yes	0%	•			
9.	Solid waste management & disposal	Yes	0%	ē			
10.	Water conservation, rainwater harvesting	Yes	0%				
11.	Energy Management	Yes	0%	•			
12.	Fire protection and fire safety requirements	Yes	30%	•			
13.	Electrical meter room, substation, receiving station	Yes	0%	•3			
14.	Others (option to add more)	-					

Thanking you, Yours faithfully, For En-Con

Licensed Engineer

SANJAY S. NARANG REGISTERED ENGINEER (Regn.No.VVCMC/ENGR/01) Agreed & Accepted by:

ghange of Promoter

Name: Date: