## PYLON PROJECTS CONSULTANTS

## ARCHITECTS, ENGINEERS, INTERIOR DESIGNERS

PPC/963/162/2017

30<sup>th</sup> June, 2017

To Shri Mohan T. Kukreja of M/s Kukreja Construction Co. Laalasis Plot No. 219, 11<sup>th</sup> Road Chembur, Mumbai 400 071

Subject: Certificate of Percentage of Completion of Construction work of Building to be known as "Geetanjali" (Maha RERA Registration Number to be obtained) situated on the land bearing CTS No. 1098, Plot No. 184, SS III, 15<sup>th</sup> Road, of Village Chembur, Taluka Kurla, M.S.D, M/West Ward, demarcated by its boundaries (latitude and longitude of the end points) by the 15<sup>th</sup> road towards North side, the South property belong to Purva & Ors., by Plot No. 183 towards East and by Plot No. 185 towards West. The plot under reference admeasures 810.00 sq.mts. area being developed by Shri Mohan T. Kukreja of M/s Kukreja Construction Co.

Sir,

I Shri P.R.Doshi of M/s Pylon Projects Consultants have undertaken assignment as Architect for certifying Percentage of Completion of Construction Work of Building to be known as "Geetanjali" situated on the land bearing CTS No. 1098, Plot No. 184, SS III, 15<sup>th</sup> Road, of Village Chembur, Taluka Kurla, M.S.D, M/West Ward The plot under reference admeasures 810.00 sq.mts. area being developed by Shri Mohan T. Kukreja of M/s Kukreja Construction Co.

- 1. Following technical professional are appointed by Owner/Promoter
  - (i) Shri. P.R.Doshi as Architect
  - (ii) Shri H.R.Mahimtura as Structural Consultant
  - (iii) Shri. Sunil Shroff / Shri Hitesh Sanghvi as MEP Consultant
  - (iv) Shri Manohar Kamble as Site Supervisor

Based on site Inspection , with respect to each of the Building of the aforesaid Real Estate Project, I certify that as per the date of this certificate, the Percentage of Work done for each of the building of the Real Estate Project as registered vide number (to be obtained) under Maha RERA is as per Table A herein below. The percentage of the work executed with respect to each of the activity of the entire phase is detailed in Table B

.2

**-**2-

TABLE A

Sr.No.	Tasks/Activity	Percentage of work done	
1	Excavation	100% work completed	
2	No of Basement(s) and Plinth	NA	
3	No. of Podiums	NA	
4	Stilt Floor	100% Work completed	
5	No. of Slabs of Super Structure	11 <sup>th</sup> slab completed (100%)	
6	Internal walls, Internal plaster,	90% work completed	
	Floorings within Flats/premises,	- French	
	Doors and Windows to each of the Flat/Premises		
7	Sanitary Fittings within the Flat/Premises	20% work completed	
	Electrical fittings within the Flat /premises		
8	Staircases, Lift Wells and Lobbies a each floor level	100% work completed	
	connecting Staircases and Lifts Overhead and		
	Underground Water Tanks		
9	The external plumbing and external plaster ,elevation	Overall completion of 75%	
	,completion of terraces with waterproofing of the		
	Building/Wing	·	
10	Installation of Lifts, water pumps, Fire Fighting	Overall completion of 50%	
	Fittings and Equipment as per CFO NOC, electrical	The state of the	
	fittings to common areas, electro, mechanical		
	equipment, compliance to conditions of		
	environment/CTZ NOC, finishing to entrance lobby/s,		
	plinth protection, paving of areas appurtenant to		
	Buildings/Wing, compound wall and all other		
	requirements as may be required to Obtain		
	Occupation/Completion Certificate		

TABLE B

Internal & External Development works in respect of the entire Registered Phase

S.No.	Common Areas and	Proposed	Percentage of work done	Details
	Facilities Amenities	Yes/No.		
1	Internal road and Footpaths	NA	NA	NA
2	Water Supply	Yes	Plug connection permission granted by MCGM u/no. AW/2227/C.HOU/NOC dated 13.3.2015	Will be complied after obtaining OC

3	Company	37	Di	
3	Sewerage	Yes	Plug connection permission	Will be complied after
	(chamber, lines,		for drainage granted by	obtaining OC
	septic tank, STP)		MCGM u/no.	
			ACM/W/928/AE(M) dated	
			26.4.2017 and SP&D NOC	
			u/no. Dy.Ch.E.SP/110/M/W	·
			dated 2.12.2016	
4	Storm Water	Yes	Yet to be started	MCGM has granted remarks
	Drains	*		u/no.
				Dy.Ch.E/3109/SWD/ES
	·.	·		dated 06.4.2015
5	Landscaping and	Yes	100% completed (No Tree	Brihanmumbai Mahanagar
	Tree Planting		cutting nor transplantation	Palika has granted NOC
			required)	u/no. Dy.SG/TA/50/ES dated
				14.7.2015. Tree completion
				NOC will be obtained before
				OC
6	Street Lighting	No	. NA	NA
7	Community	No	NA	NA
	Buildings			
8	Treatment and	No	NA	NA
	disposal of			
	sewerage and	·		
	sullage water			
9	Solid Waste	No	NA	NA
	Management &			<u>-</u>
	Disposal			
10	Water	Yes	Yet to be started	We have obtain drawings and
	Conservation, Rain			details for completion of
	water harvesting			Rain Water Harvesting from
				Dr. Amar N. Joshi
				(Geologist)
11	Energy	No	NA	NA NA
	Management	1,0	1471	INA
L	1			

12	Fire protection and fire safety requirements	Yes	50% fitting completed	MCGM has granted CFO NOC u/no. FB/HR/R-V/120 dated 17.08.2015. Completion will be obtained before OC
13	Electrical meter room, sub station, receiving station	Yes	Electrical meter room- 100% completed Sub Station not required	Reliance Infrastructure Ltd. has granted NOC u/no. NOCNOS/UNIT/17/2016/ C00001019 381128

Yours faithfully, For Pylon Projec

jects Consultants

P.R.Dyshi Architect CA/80/5549