

Date: 30/07/2017

Ref.:

Table A
Building No. 2 / Type R13-B Wing

Sr. No.	Task / Activity	Percentage of work done
1	Excavation	100 %
2	Number of basements 01 and plinths	100%
3	Number of podiums	Nil.
4	Stilt floor	50%
5	No of slabs 08 of super structure	100 %
6	Internal walls, Internal plaster Flooring with in flats/ premises Doors and windows to each of the flats/ premises	50%
7	Sanitary fittings within the flats/ premises Electrical fittings within the flats/ premises	Nil
8	Staircases, Lifts wells and lobbies at each floor level connecting staircases and lifts Overhead and Underground water tanks.	100%
9	The external plumbing and external plaster, elevation, completion of terraces with waterproofing of Building/ Wing.	100%
10	Installation of lifts, water pumps, Fire fighting fittings and Equipment as per CFO NOC, Electrical fittings to common areas, electro mechanical equipment, Compliance to conditions of environment/ CRZ NOC Finishing to entrance lobby, plinth protection, paving areas appurtenant to Building/ Wing Compound wall and all other requirements as may be required to obtain occupation/ completion certificate.	Nil


 30.7.17