FORM 1

ARCHITECT'SCERTIFICATE

Date:

To Sheraton Holidays LLP, 404, Maheshwari Building, Business Suite 9, Near Dynasty Restaurant, Santacruz West, Maharashtra, 400054.

Subject:

Certificate of percentage of completion of construction work of 1 No. of Building the 'BOHO BLISS ' project (Goa RERA Registration Number-----) Situated on the plot bearing Survey No.190/7-B of Calangute Village, Bardez North Goa, Goa demarcated by its boundaries (Latitude and longitude of the end points)

East

: by property bearing survey no.19/9 Village Calangute; : by property bearing survey no.19/7 Village Calangute;

West North

: By Village Panchayat Road;

South

: by property bearing survey no.19/8 Village Calangute admeasuring 841.0 sq. mts. area being developed by Sheraton Holidays LLP.

C - DED	Registration	NT 1	
-O2 KHK /			

Sir,

I Mr. Ezra Bosco Dsouza have undertaken assignment as Architect of certifying percentage of Completion of Construction work of the 1 No. of Building of the BOHO BLISS Project, situated on the plot bearing Survey No. 190/7-B of Calangute Village, Bardez North Goa, Goa admeasuring 841.0 sq. mts. area being developed by Sheraton Holidays LLP.

- 1. Following technical professionals are appointed by Owner / Promoter:-
- (i) Mr. Ezra Bosco Dsouza as Architect;
- (ii) Mr. Auxilio J.S. Rodrigues as Structural Consultant
- (iii) SR Design Hub as MEP consultant
- (iv) Mithun Sarkar as Site Supervisor

Based on Site Inspection, with respect to each of the building/wing of the aforesaid Real Estate project, I certify that as on the date of this certificate, the percentage of work done for each of the building/wing of the Real Estate project as registered vide number N/A under Goa RERA is as per table A herein below. The percentage of the work executed with respect to each of the activity of the entire phase is detailed in table B

Table A

Building/Wing Number_(to be prepared separately for each Building/Wing of the Project)

Sr. No	Task/Activity	Percentage Of work done
1	Excavation	0%
2	Number of basement(s) and plinth	0%
3	Number of Podiums	NA
4	Stilt Floor	0%
5	Number of Slabs Of Super Structure	0%
6	Internal Walls ,Internal Plaster, Floorings Within Flats / Premises, Doors and Windows to each of the Flat / Premises	0%
7	Sanitary Fittings Within the Flat/Premises, Electrical Fittings Within the Flat/Premises	0%
8	Staircases, Lifts Wells and Lobbies at each Floor level connecting staircases and Lifts, Overhead and Underground Water Tanks	0%
9	The external plumbing and external Plaster, Elevation, completion of terraces with waterproofing of the building / wings,	0%
10	Installation of Lifts, Water pumps, Fire Fighting Fittings and Equipment as per CFO NOC, Electrical Fittings to Common areas, electro, Mechanical Equipments, Compliance to conditions of environment / CRZ NOC, Finishing to entrance Lobby/s, plinth Protection, Paving of areas appurtenant to Building/Wing, Compound wall and all other requirements as may be required to obtain Occupation / Completion Certificate	0%

Table B

Internal & External Development Works in respect of the entire Registered Phase

Sr.No	Common areas and Facilities, Amenities	Proposed (Yes/No)	Percentage Of Work Done	Details
1	Internal Roads and Footpaths'	YES	0%	_
2	Water Supply	YES	0%	* - s
3	Sewerage(chamber, Lines, Septic Tank, STP)	YES	0%	-
4	Storm Water Drains	YES	0%	.=
5	Landscaping & Tree Planting	YES	0%	-
6	Street Lighting	YES	0%	-
7	Community Buildings	NO	NA	-
8	Treatment and Disposal of Sewage And Sullage water	NO	NA	-
9	Solid Waste Management & Disposal	YES	0%	- · · · · · · · · · · · · · · · · · · ·
10	Water Conservation , Rain water harvesting	NO	NA	
11	Energy Management	NO	NA	- , , ,
12	Fire Protection And Fire safety Requirements	YES	0%	
13	Electrical meter R room, Sub-station, Receiving station	YES	0%	=
14	Others (Option to Add more)	NO	NA	

Ar. EZRA D'SOUZA
TCP REG. NO. AR/0028/2015
COA REG. NO. CA/2013/60717
COA REG. NO. CA/2013/60717
Ezra Bosco Dsouza