FORM 1

ARCHITECT'S CERTIFICATE

(For withdrawal of Money from Designated Account)

Date:20-04-2018

To

The

SINGLA BUILDERS & PROMOTERS LTD. VILL-DESUMAIRA, CHD ROAD KHARAR SAS NAGAR PUNJAB

No./Survey no./		79-PR0096] situat	ted on the Plot be	DERABASSI [RERA
Division _	village DEDADAGE	to the South	to the East	to the Wart 6
63122,26 sq.m	area being develope	ed by [Promoter's SIN	ol District <u>SAS NA</u> NGLA BUILDERS &	AGAR_admeasuring PROMOTERS LTD.

I/ We_A+D DESIGN STUDIO have undertaken assignment as Architect of certifying Percentage of Completion of Construction Work for the project above.

- 1. Following technical professionals are appointed by Owner / Promoter :-
 - M/s /Shri / Smt BACHAN SINGH as PROJECT MANAGER. (ii)
 - M/s /Shri / Smt MANU BANSAL as (PROJECT ENGINEER)Site Supervisor

Based on Site Inspection, with respect to each of the Building/Wing of the aforesaid Real Estate Project, I certify that as on the date of this certificate, the Percentage of Work done for each of the building/Wing of the Real Estate Project as registered vide number PBRERA-SAS79-PR0096 under RERA, Punjab, is as per table A herein below. The percentage of the work executed with respect to each of the activity of the entire phase is detailed in Table B.



-	Task/ Activity	Percentage of work	TABLE A Work to be done
	Excavation	done	work to be done
2	number of Bacoments	100 %	
_		100 %	
3	number of Podi		
4.	JUIL Floor		
5,	12number of Slabs of	100 %	-
	Super Structure	80 %	-
6.	Internal walls, Internal Plaster,		20%
	Doors and Windows to each of the Flat/Premises	75 %	25%
7.	Sanitary Fittings within the Flat/Premises, Electrical Fittings within the Flat/Premises	45%	55%
8.	Staircases, Lifts Wells and Lobbies at each Floor level connecting Staircases and Lifts, Overhead and Underground Water Tanks	50 %	50%
9.	elevation, completion of terraces with waterproofing of the Building/Wing	40 %	60%
10.	Installation of lifts, water pumps, Fire Fighting Fittings and Equipment as per CFO NOC, Electrical fittings to Common Areas, electro, mechanical equipment, Compliance to conditions of environment /CRZ NOC, Finishing to entrance, Lobby/s, plinth protection, paving of areas appurtenant to Building/Wing, Compound Wall, and all other requirements as may be required to Obtain Occupation /Completion Certificate	40%	60%



TABLE-B

Internal & External Development Works In Respect Of The Entire Registered Phase

o Common areas and Facilities, Amenities	Proposed (Yes/No)	Percentage of Work done	Details
Internal Roads &	VEC		
Footpaths	123	50%	In progress
Water Supply	YES	F00/	
Sewerage		30%	In progress
(chamber, lines, Septic Tank,	YES	100%	
STP)			
Storm Water	YES	1000	
Drains		100%	
Landscaping &	YES		
Tree Planting		70%	In progress
Street Lighting	YES	40 %	
Community	YES		In progress
Buildings		95%	
Treatment and			In progress
disposal of sewage and	YES	100%	
ullage water			
	and Facilities, Amenities Internal Roads & Footpaths Water Supply Sewerage (chamber, lines, Septic Tank, STP) Storm Water Drains Landscaping & Tree Planting Street Lighting Community Buildings Treatment and disposal of sewage and	and Facilities, Amenities Internal Roads & YES Footpaths Water Supply YES Sewerage (chamber, lines, YES Septic Tank, STP) Storm Water YES Drains Landscaping & YES Tree Planting Street Lighting YES Community YES Buildings Treatment and disposal of YES Sewage and	and Facilities, Amenities Internal Roads & YES 50% Footpaths Water Supply YES 50% Sewerage (chamber, lines, YES 100% Septic Tank , STP) Storm Water YES 100% Drains Landscaping & YES 70% Tree Planting Street Lighting YES 40 % Community YES 95% Buildings Treatment and disposal of Sewage and

Ar. Tripg/Girdhar CA/2489/44080

	Solid Waste management 9. Disposal	&			
-	147.		YES	100%	
	Water conserv 10. Rain water har	vation, vesting	YES	90%	
1	 Energy manage 	ment	YES		In progress
12	Fire protection fire safety requirements	and	YES	50%	
	Electrical meter	room,		50%	In progress
13.	Once I		YES	50%	In progress
14.	parks Roads	19	YES	100%	
15.	Common Lobbies of entrance, staircase landings, verandah		YES	70%	
16.	Staircases		YES		In progress
	Common Open terr	ace	. 23	70%	In progress
17.	uncovered (if cover then not exempted)	ed	YES	90%	In progress
	Common Basement		NO		, 10,000
	Stilt area / podium parking	,	/ES	50%	In progress
w. r.	Covered parking / garages	Y	ES	50%	In progress



2	Open parking area 1. (uncovered)			
		YES	20%	
22	Club Houses / recreational building			In progress
Swimming Bank	Swimming Pool	YES	95%	In progress
23.	(Constructed area,			
		YES	100%	
24.	Water tanks sumps and related apparatuses			
		YES	50%	In progress
25.	Common Store rooms and area required for storing maintenance material etc	NO		In progress

Av. Sipat Girdhar Signature of A chitect

Name Ar. Tripat airdhar

Address

Sec-34 A ((40)

Aadhar No. 8686 9429 8361

Pan no. AKUPa4025 t A/2009/44080

(License No or Authority.....)