

FORM 1
ARCHITECT'S CERTIFICATE

Date: 23/03/2022

To, SAI SHARDDHA AASOCIATES S. No. 176, Choudhari Park, Lamelosa, Wakad, Pune 411057

Subject: Certificate of percentage of completion of construction work of the A & B of the Project name Lamelosa Phase of the project [RERA Registration Number P52100014890] situated on the plot bearing Sr. NO. 176/1/1& 127(p) Demarcated by its boundaries(Latitude 18.605255° Longitude73.761565°) Sr. No. 176(p) to the North, Sr. No. 176(p) to the South, Sr. No. 176(P) to the East, Sr. No.176 (p), 127(p) & 12.00 M.W. Road to the West of Division Pune villageWakadtaluka MulashiDistrict Pune PIN 411057 admeasuring 4700.00sq. m.area being developed by SAI SHARDDHA AASOCIATES.

Sir,

I Ar. Sangram Salunke have undertaken assignment as Architect/Licensed surveyor of certifying percentage of completion of construction work of the buildings A & B of the Project name Lamelosa Phase of the project situated on the plot bearing Sr. NO. 176/1/1& 127(p) Of Division Pune villageWakadtaluka MulashiDistrict Pune PIN 411057 admeasuring 9400.00sq. m.area being developed by SAI SHARDDHA AASOCIATES.

- 1. Following technical professionals are appointed by owner/promoter: -
- (i) Shri Ar. Sangram Salunke Architect;
- (ii) Shri Narendra Waghilaas Site Supervisor
- (iii) M/S. GENSYS TECHNOLOGIES PVT LTDas structural consultants

Based on Site Inspection, with respect to each of the Building/Wing of the aforesaid Real Estate project, I certify that as on the date of this certificate, the percentage of work done for each of the building/wing of the Real Estate Project as registered vide number P52100014890RERA is as per table A Herein below. The percentage of the work executed with respect to each of the major activity of the Building/Wing and overall percentage of work done with respect to each Building/Wing is detailed in the Table B.

Ar. SANGRAM SALUNKE

CA/18/91601



Table A Wing- A

Sr. No	Task /Activity	Percentage of Work completed	
1	Excavation		
2	1 no of Plinths	100%	
3	13 numbers of Slabs of super structure	100%	
4	External walls, Internal Walls, Internal Plaster, Flooring within flats, Doors & windows to each flat	100%	
5	Sanitary Fittings, Electrical fittings within the flat	100%	
6	Staircase, Lift Wells, Lobbies at each level connecting staircases and lifts, overhead and underground water tanks	100%	
7	External Plumbing and External Plaster, elevation, completion of terraces with water proofing of wings	95%	
8	Installation of lifts, water pumps, firefighting fittings and equipment's as per CFO NOC, electrical fittings to common areas, electro mechanical equipment's, compliance to conditions of environment /CRZ NOC, Finishing to entrance lobby's, plinth protection, paving of areas appurtenant to building/wing, compound wall, and all other requirements as may be required to obtain Occupancy/ completion Certificate	95%	

Ar. SANGRAM SALUNKE CA/18/91601



Architects & Interior Designers

Sr. No	Wing- B Task / Activity	Percentage of Work completed 100%	
1	Excavation		
2	1 no of Plinths	100%	
3	13 numbers of Slabs of super structure	100%	
4	External walls, Internal Walls, Internal Plaster, Flooring within flats, Doors & windows to each flat	100%	
5	Sanitary Fittings, Electrical fittings within the flat	100%	
6	Staircase, Lift Wells, Lobbies at each level connecting staircases and lifts, overhead and underground water tanks	95%	
7	External Plumbing and External Plaster, elevation, completion of terraces with water proofing of wings	95%	
8	Installation of lifts, water pumps, firefighting fittings and equipment's as per CFO NOC, electrical fittings to common areas, electro mechanical equipment's, compliance to conditions of environment /CRZ NOC, Finishing to entrance lobby's, plinth protection, paving of areas appurtenant to building/wing, compound wall, and all other requirements as may be required to obtain Occupancy/ completion Certificate	50%	

Ar. SANGRAM SALUNKE CA/18/91601



Architects & Interior Designers

Table B
Internal & External Development works in Respect of the entire registered phase

Sr،	Common Area And	Proposed	Percentage Of	Details
No.	Facilities, Amenity	(Yes/No)	Work Done	
1.	Solid Waste Management And Disposal	Yes	%	Garbage Chute With Room Provide After Completion
2.	Water Conservation, Rain water Harvesting	Yes	%	Rain water Harvesting Provide After Completion
3.	Energy management	Yes	90%	Solar Water As Per PCMC Norms Provide After Completion
4.	Fire Protection And Fire Safety Requirements	Yes	100%	As Per Fire Department Norms Provide After Completion
5.	Internal Roads & Footpaths	Yes	100%	Internal Road & Marginal Drive way In Concrete
6.	Water Supply	Yes	100%	Bore well & PCMC Waterline After Completion
7.	Street Lighting	Yes	100%	As Per PCMC Norms
8.	Electrical Meter Room, Sub-Station, Receiving Station	Yes	100%	As Per MSEDCL
9.	Open Parking	Yes	%	Provide After Completion
10.	Community Buildings	Yes	75%	Only Club House
11.	Treatment And Disposal Of Sewage And Sullage Water	NA	NA	NA
12.	Sewerage (Chamber, Lines, Septic Tank, STP)	Yes	100%	As Per PCMC Norms
13.	Storm Water Drains	Yes	100%	As Per PCMC Norms
14.	Landscaping & Tree Planting	Yes	%	As Per PCMC Norms & Consultant

Ar. SANGRAM SALUNKE CA/18/91601