

## Ashwinikumar Prabhu

C-5, 3rd floor, Trionora Apts., Near Municipal Market, Panaji - Goa 403 001 INDIA Ph.: 0091 832 6511330 B-209, 2nd floor, Saldanha Business Towers, At Court Circle, Mapusa, Goa, 403507 INDIA Ph.: 0091-832-6516650

Cell: 9422445email: studioarchetype@gmail.o web: http://www.studioarchetype.co

#### FORM 1

### ARCHITECT'S CERTIFICATE

Date: 21 February 2018

To, C-27 Pamposh Enclave New Delhi Preeti Infratech LLP

Subject: Certificate of Percentage of Completion of Construction Work of Three (3)No. of Buildings (s) of the Project situated on the Plot bearing Survey no. 175 sub division no. 32, demarcated by its boundaries Property bearing Survey no. 175 sub division no. 30 to the North, Public Road to the East, Property bearing Survey no. 175 sub division no. 35 to the South, Survey no. 175 sub division no. 31 to the West, of Siolim Village, Taluka Bardez, District North Goa, PIN 403 507 admeasuring 3750 sq.mts. area being developed by Preeti Infratech LLP.

	Ref: Goa RE	RA Registration Number
	Sir,	
	I, Ashw	rinikumar Prabu have undertaken assignment as Architect of certifying Percentage of Completion of
	Construction	Work of the Three (3) Buildings of the Entire Phase of the Project, situated on the plot bearing, of
	Survey no. 1	75 sub division no. 32, Siolim Village, Taluka Bardez, District North Goa, admeasuring 3750 sq.mts.
	area being d	leveloped by Preeti Infratech LLP.
1	1. Follo	owing technical professionals are appointed by Owner / Promoter :
	(i)	Shri Ashwinikumar Prabhu as Architect
	(ii)	Shri Rajesh Mahambrey as Structural Consultant
	. (iii)	M/s /Shri / Smt. —————— as MEP Consultant
	(iv)	M/s /Shri / Smt. ————————————————————————————————————
	Based on Sit	e Inspection, with respect to each of the Building/Wing of the aforesaid Real Estate Project , I certify

that as on the date of this certificate, the Percentage of Work done for each of the building of the Real Estate

Project as registered vide number \_\_\_\_\_\_ under GoaRERA is as per table A herein below. The

percentage of the work executed with respect to each of the activity of the entire phase is detailed in Table B.

C-5, 3rd floor, Trionors Apts., Near Municipal Market, Panall - Goz 403 001 INDIA Ph.: 0091 832 6511330 8-209, 2nd floor, Saldanha Business Towers, At Court Circle, Mapusa, Gos., 403507 INDIA Ph.: 0091-832-6516650

Cell: 9422445450
email: studioarchetype@gmail.com
web: http://www.studioarchetype.com

#### TARLE-A

### Building Number Block - A

ar-ejar.

Park Alle

Sr. No.	Tasks / Activity	Percentage of work done
オキナナ	Excavation .	100%
	One(1) Number of Plinth	80 %
<b>3</b> ,	NIL number of Podiums	NA
4.	Stilt Floor	0%
<b>5.</b>	Five (3) number of Slabs of Super Structure	0 %
6.	Internal Walls, Internal Plaster, Floorings within Flats/Premises, Doors and Windows to each of the Flat/Premises.	0%
	Sanitary Fittings within the Flat/Premises, Electrical Fittings within the Flat/Premises.	0%
8.	Staircases, Lifts Well sand Lobbies at each Floor level connecting Staircases and Lifts, Overhead and Underground Water Tanks.	0%
9.	The external plumbing and external plaster, elevation, completion of terraces with waterproofing of the Building/Wing.	0%
10.	Installation of lifts, water pumps, Fire Fighting Fittings and Equipment as per CFO NOC, Electrical fittings to Common Areas, electro, mechanical equipment, Compliance to conditions of environment /CRZ NOC, Finishing to entrance lobby/s, plinth protection, paving of areas appurtenant to Building/Wing, Compound Wall and all other requirements as may be required to obtain Occupation / Completion Certificate.	



## Ashwinikumar Prabhu

C-5, 3rd floor, Trionors Apts., Near Municipal Market, Panaji - Gos 403 001 INDIA Ph.: 0091 832 6511330 B-209, 2nd floor, Saldanha Business Towers, At Court Circle, Mapusa, Gos, 403607 INDIA Ph.: 0091-832-6516650

Cell : 9422445450 email : studioarchetype@gmail.com web : http://www.studioarchetype.co.m

### Building Number Block -B

Sr. No.	Tasks /Activity	Percentage of work done
	Excavation	100 %
1.	One(1) Number of Plinth	100 %
3.	Nil number of Podiums	NA NA
4	Stilt Floor	0%
	Five (3) number of Slabs of Super Structure	33 %
	Internal Walls, Internal Plaster, Floorings within Flats/Premises, Doors and Windows to each of the Flat/Premises.	0 %
(1) (1) (1) (1) (1) (1) (1) (1) (1) (1)	Sanitary Fittings within the Flat/Premises, Electrical Fittings within the Flat/Premises.	0 %
	Staircases, Lifts Well sand Lobbies at each Floor level connecting Staircases and Lifts, Overhead and Underground Water Tanks.	0%
3.	The external plumbing and external plaster, elevation, completion of terraces with waterproofing of the Building/Wing.	0%
	Installation of lifts, water pumps, Fire Fighting Fittings and Equipment as per CFO NOC, Electrical fittings to Common Areas, electro, mechanical equipment, Compliance to conditions of environment /CRZ NOC, Finishing to entrance lobby/s, plinth protection, paving of areas appurtenant to Building/Wing, Compound Wall and all other requirements as may be required to obtain Occupation / Completion Certificate.	0%

# Ashwinikumar Prabhu architect

C-5, 3rd floor, Trionora Apla., Near Municipal Market, Panaji - Gos 403 001 INDIA Ph : 0091 832 6511330 B-209, 2nd floor, Saldanha Business Towers, At Court Circle, Mapusa, Gos, 403507 INDIA Ph.: 0091-832-6516650

Cell 9422445450
email: studioarchetype@gmail.cxn
web\_http://www.studioarchetype.com

### **Building Number Block -C**

Sr. No.	Tasks / Activity	Percentage of work done
1.1	Excavation	100 %
2.	One(1) Number of Plinth	100 %
3.	Nil number of Podiums	NA
4.	Stilt Floor	0%
5.	Five (3) number of Slabs of Super Structure	0%
	Internal Walls, Internal Plaster, Floorings within Flats/Premises, Doors and Windows to each of the Flat/Premises.	0 %
7.	Sanitary Fittings within the Flat/Premises, Electrical Fittings within the Flat/Premises.	0 %
	Staircases, Lifts Well sand Lobbies at each Floor level connecting Staircases and Lifts, Overhead and Underground Water Tanks.	0%
<b>9.</b>	The external plumbing and external plaster, elevation, completion of terraces with waterproofing of the Building/Wing.	0 %
10.	Installation of lifts, water pumps, Fire Fighting Fittings and Equipment as per CFO NOC, Electrical fittings to Common Areas, electro, mechanical equipment, Compliance to conditions of environment /CRZ NOC, Finishing to entrance lobby/s, plinth protection, paving of areas appurtenant to Building/Wing, Compound Wall and all other requirements as may be required to obtain Occupation / Completion Certificate.	0%

C-5, 3rd floor, Trionora Apts., Near Municipal Market, Panali - Gos 403 001 INDIA Ph.: 0091 832 6511330 B-209, 2nd floor, Saldanha Business Towers, At Court Circle, Mapusa, Gos, 403507 INDIA Ph.: 0091-832-6516650

TABLE-B

Internal and External Development Works in respect of the entire Registered Phase.

	Internal and External Developm	Proposed	Percentage of	Details
No.	Common areas and Facilities, Amenities	(Yes/No)	Work done	and the second s
	Internal Roads & Pathway.	Yes	0%	The second secon
	#4 - Fine	Yes	0%	4
2.	Water Supply		0%	
3.	Sewerage (chamber, lines, Septic Tank ,	Yes		
	Storm Water Drains	Yes	0%	
4, 5.	Landscaping& Tree	Yes	0%	
	Planting.	Yes	0%	
6.	Street Lighting	Ves	0%	
7.	Community Buildings		12 NA .5 1	
8.	Treatment and disposal of sewage and sullage water.	No.		•
9.	sewage and sunage work. Solid Waste management &			
	Oisposal.	NO	The second secon	
10	harvesting	NO	NA NA	
111			NA NA	
1	Fire protection and fire safety	NO		
1	requirements 3. Electrical meter room, sub-	Yes	0*	e sy many e-many from this
	station, receiving station.	Yes	08	
1	4. Others ( Option to A22 Swimming Pool & Club House			

ARCH. ASHWINIKUMAR PRABHU

TCP Reg. No. AR/0029/2010