

Form-1
ARCHITECT'S CERTIFICATE

Date: 10/05/2023

To,
VRAJ CORPORATION
2nd Floor, Maruti Arcade,
Shivranjani Cross Road,
Above Pintoo Garments,
132ft Ring Road, Satellite,
Ahmedabad – 380015.

Subject:- Certificate of Percentage of Completion of Construction Work of "Poonam Pride" 19 No. of Building(s) A, B, C, D, E, E1, F, G, H, I, J, K, L, M, N, O, P, Q, R Wing(s) of the Single Phase of the Project (Gujarat RERA Registration Number PR/GJ/AHMEDABAD/AHMEDABAD CITY/AUDA/RAA02979/EX2/270522) situated on the Plot bearing C.N. No./CTS No./Survey no./Final Plot no.25, T.P No. 1(Shela) demarcated by its boundaries FP 43/2, 44 to North 18 M.T.TPS Road to the South FP22/2, 23/1 to the East FP 27, 28, 42 to the West of Division, village Shela, taluka Sanand, District Ahmedabad, PIN 350058, admeasuring 40,742.99 Sq.mts. area being developed by **Vraj Corporation**.

Sir,
I **Caleb Ferro** have undertaken assignment as Architect of certifying Percentage of Completion of Construction Work of the 19 No. of Building(s) A, B, C, D, E, E1, F, G, H, I, J, K, L, M, N, O, P, Q, R Wing(s) of the Single Phase of the Project, situated on the plot bearing C.N. No./CTS No./Survey no. /Final Plot no. 25 OF D.T.P No.1 (Shela) demarcated by its boundaries FP 43/2, 44 to North 18 M.T.TPS Road to the South FP22/2, 23/1 to the East FP 27, 28, 42 to the West of Division, village Shela, taluka Sanand, District Ahmedabad, PIN 350058, admeasuring 40,742.99 Sq.mts. area being developed by **Vraj Corporation** as per the approved plan.

1. Following technical professionals are appointed by Owner/Promoter:- (as applicable)
 - (i) Shri Nilesh R Suthar as Engineer.
 - (ii) Shri Haresh A. Shah as Structural Consultant
 - (iii) M/s. Malnglam Electric & Vimrsh Consultan as MEP Consultant
 - (iv) Shri Nimesh Kulkarni as Site Supervisor/Clerk of Works

Based on Site Inspection by undersigned on **10/05/2023** date and with respect to each of the Building/Wing or of the plots as the case may be of the afore said Real Estate Project, I certify that as on the date of this certificate, the Percentage of Work done for each of the building/Wing of the Real Estate Project as registered vide number PR/GJ/AHMEDABAD/AHMEDABAD CITY/AUDA/RAA02979/EX2/270522 under GujRERA is as per table A herein below. The percentage of the work executed with respect to each of the activity of the entire phase is detailed in Table A and B.



AR CALEB FERRO
CA | 2015 | 69608


Table – A

Building/Wing Number A

Sr. No.	Tasks/Activity	Percentage of work done
1	Excavation	100%
2	0 number of Basement(s) and Plinth	N/A
3	0 number of Podiums	N/A
4	Stilt Floor	N/A
5	3 number of Slabs of Super Structure	100%
6	Internal walls, Internal Plaster, Floorings within Flats/Premises, Doors and Windows to each of the Flat/Premises	100%
7	Sanitary Fittings within the Flat/Premises	100%
8	Staircases, Lifts Wells and Lobbies at each Floor level connecting Staircases and Lifts, Overhead and Underground Water Tanks	100%
9	The external plumbing and external plaster, elevation, completion of terraces with waterproofing of the Building/Wing.	100%
10	Installation of lifts, water pumps, Fire Fighting Fittings and Equipment as per CFO NOC, Electrical fittings to Common Areas, electro, mechanical equipment, compliance to conditions of environment/CRZ NOC, Finishing to entrance lobby/s, plinth protection, paving of areas appurtenant to Building/Wing, Compound Wall and all other requirements as may be required to Obtain Occupation/Completion Certificate	100%

Building/Wing Number B

Sr. No.	Tasks/Activity	Percentage of work done
1	Excavation	100%
2	0 number of Basement(s) and Plinth	N/A
3	0 number of Podiums	N/A
4	Stilt Floor	N/A
5	3 number of Slabs of Super Structure	100%
6	Internal walls, Internal Plaster, Floorings within Flats/Premises, Doors and Windows to each of the Flat/Premises	100%
7	Sanitary Fittings within the Flat/Premises	100%
8	Staircases, Lifts Wells and Lobbies at each Floor level connecting Staircases and Lifts, Overhead and Underground Water Tanks	100%
9	The external plumbing and external plaster, elevation, completion of terraces with waterproofing of the Building/Wing.	100%
10	Installation of lifts, water pumps, Fire Fighting Fittings and Equipment as per CFO NOC, Electrical fittings to Common Areas, electro, mechanical equipment, compliance to conditions of environment/CRZ NOC, Finishing to entrance lobby/s, plinth protection, paving of areas appurtenant to Building/Wing, Compound Wall and all other requirements as may be required to Obtain Occupation/Completion Certificate	100%



 AR CALEB FERRO
 CA | 2015 | 69608

Building/Wing Number C

Sr. No.	Tasks/Activity	Percentage of work done
1	Excavation	100%
2	0 number of Basement(s) and Plinth	N/A
3	0 number of Podiums	N/A
4	Stilt Floor	N/A
5	3 number of Slabs of Super Structure	100%
6	Internal walls, Internal Plaster, Floorings within Flats/Premises, Doors and Windows to each of the Flat/Premises	100%
7	Sanitary Fittings within the Flat/Premises	100%
8	Staircases, Lifts Wells and Lobbies at each Floor level connecting Staircases and Lifts, Overhead and Underground Water Tanks	100%
9	The external plumbing and external plaster, elevation, completion of terraces with waterproofing of the Building/Wing.	100%
10	Installation of lifts, water pumps, Fire Fighting Fittings and Equipment as per CFO NOC, Electrical fittings to Common Areas, electro, mechanical equipment, compliance to conditions of environment/CRZ NOC, Finishing to entrance lobby/s, plinth protection, paving of areas appurtenant to Building/Wing, Compound Wall and all other requirements as may be required to Obtain Occupation/Completion Certificate	100%

Building/Wing Number D

Sr. No.	Tasks/Activity	Percentage of work done
1	Excavation	100%
2	0 number of Basement(s) and Plinth	N/A
3	0 number of Podiums	N/A
4	Stilt Floor	N/A
5	3 number of Slabs of Super Structure	100%
6	Internal walls, Internal Plaster, Floorings within Flats/Premises, Doors and Windows to each of the Flat/Premises	100%
7	Sanitary Fittings within the Flat/Premises	100%
8	Staircases, Lifts Wells and Lobbies at each Floor level connecting Staircases and Lifts, Overhead and Underground Water Tanks	100%
9	The external plumbing and external plaster, elevation, completion of terraces with waterproofing of the Building/Wing.	100%
10	Installation of lifts, water pumps, Fire Fighting Fittings and Equipment as per CFO NOC, Electrical fittings to Common Areas, electro, mechanical equipment, compliance to conditions of environment/CRZ NOC, Finishing to entrance lobby/s, plinth protection, paving of areas appurtenant to Building/Wing, Compound Wall and all other requirements as may be required to Obtain Occupation/Completion Certificate	100%


AR CALEB FERRO
 CA | 2015 | 69608

Building/Wing Number E

Sr. No.	Tasks/Activity	Percentage of work done
1	Excavation	100%
2	0 number of Basement(s) and Plinth	N/A
3	0 number of Podiums	N/A
4	Stilt Floor	N/A
5	3 number of Slabs of Super Structure	100%
6	Internal walls, Internal Plaster, Floorings within Flats/Premises, Doors and Windows to each of the Flat/Premises	100%
7	Sanitary Fittings within the Flat/Premises	100%
8	Staircases, Lifts Wells and Lobbies at each Floor level connecting Staircases and Lifts, Overhead and Underground Water Tanks	100%
9	The external plumbing and external plaster, elevation, completion of terraces with waterproofing of the Building/Wing.	100%
10	Installation of lifts, water pumps, Fire Fighting Fittings and Equipment as per CFO NOC, Electrical fittings to Common Areas, electro, mechanical equipment, compliance to conditions of environment/CRZ NOC, Finishing to entrance lobby/s, plinth protection, paving of areas appurtenant to Building/Wing, Compound Wall and all other requirements as may be required to Obtain Occupation/Completion Certificate	100%

Building/Wing Number E1

Sr. No.	Tasks/Activity	Percentage of work done
1	Excavation	100%
2	0 number of Basement(s) and Plinth	N/A
3	0 number of Podiums	N/A
4	Stilt Floor	N/A
5	3 number of Slabs of Super Structure	100%
6	Internal walls, Internal Plaster, Floorings within Flats/Premises, Doors and Windows to each of the Flat/Premises	100%
7	Sanitary Fittings within the Flat/Premises	100%
8	Staircases, Lifts Wells and Lobbies at each Floor level connecting Staircases and Lifts, Overhead and Underground Water Tanks	100%
9	The external plumbing and external plaster, elevation, completion of terraces with waterproofing of the Building/Wing.	100%
10	Installation of lifts, water pumps, Fire Fighting Fittings and Equipment as per CFO NOC, Electrical fittings to Common Areas, electro, mechanical equipment, compliance to conditions of environment/CRZ NOC, Finishing to entrance lobby/s, plinth protection, paving of areas appurtenant to Building/Wing, Compound Wall and all other requirements as may be required to Obtain Occupation/Completion Certificate	100%



AR CALEB FERRO
 CA | 2015 | 69608

Building/Wing Number F

Sr. No.	Tasks/Activity	Percentage of work done
1	Excavation	100%
2	0 number of Basement(s) and Plinth	N/A
3	0 number of Podiums	N/A
4	Stilt Floor	N/A
5	3 number of Slabs of Super Structure	100%
6	Internal walls, Internal Plaster, Floorings within Flats/Premises, Doors and Windows to each of the Flat/Premises	100%
7	Sanitary Fittings within the Flat/Premises	100%
8	Staircases, Lifts Wells and Lobbies at each Floor level connecting Staircases and Lifts, Overhead and Underground Water Tanks	100%
9	The external plumbing and external plaster, elevation, completion of terraces with waterproofing of the Building/Wing.	100%
10	Installation of lifts, water pumps, Fire Fighting Fittings and Equipment as per CFO NOC, Electrical fittings to Common Areas, electro, mechanical equipment, compliance to conditions of environment/CRZ NOC, Finishing to entrance lobby/s, plinth protection, paving of areas appurtenant to Building/Wing, Compound Wall and all other requirements as may be required to Obtain Occupation/Completion Certificate	100%

Building/Wing Number G

Sr. No.	Tasks/Activity	Percentage of work done
1	Excavation	100%
2	0 number of Basement(s) and Plinth	N/A
3	0 number of Podiums	N/A
4	Stilt Floor	N/A
5	3 number of Slabs of Super Structure	100%
6	Internal walls, Internal Plaster, Floorings within Flats/Premises, Doors and Windows to each of the Flat/Premises	100%
7	Sanitary Fittings within the Flat/Premises	100%
8	Staircases, Lifts Wells and Lobbies at each Floor level connecting Staircases and Lifts, Overhead and Underground Water Tanks	100%
9	The external plumbing and external plaster, elevation, completion of terraces with waterproofing of the Building/Wing.	100%
10	Installation of lifts, water pumps, Fire Fighting Fittings and Equipment as per CFO NOC, Electrical fittings to Common Areas, electro, mechanical equipment, compliance to conditions of environment/CRZ NOC, Finishing to entrance lobby/s, plinth protection, paving of areas appurtenant to Building/Wing, Compound Wall and all other requirements as may be required to Obtain Occupation/Completion Certificate	100%



AR CALEB FERRO
 CA | 2015 | 69608

Building/Wing Number H

Sr. No.	Tasks/Activity	Percentage of work done
1	Excavation	100%
2	0 number of Basement(s) and Plinth	N/A
3	0 number of Podiums	N/A
4	Stilt Floor	N/A
5	3 number of Slabs of Super Structure	100%
6	Internal walls, Internal Plaster, Floorings within Flats/Premises, Doors and Windows to each of the Flat/Premises	100%
7	Sanitary Fittings within the Flat/Premises	100%
8	Staircases, Lifts Wells and Lobbies at each Floor level connecting Staircases and Lifts, Overhead and Underground Water Tanks	100%
9	The external plumbing and external plaster, elevation, completion of terraces with waterproofing of the Building/Wing.	100%
10	Installation of lifts, water pumps, Fire Fighting Fittings and Equipment as per CFO NOC, Electrical fittings to Common Areas, electro, mechanical equipment, compliance to conditions of environment/CRZ NOC, Finishing to entrance lobby/s, plinth protection, paving of areas appurtenant to Building/Wing, Compound Wall and all other requirements as may be required to Obtain Occupation/Completion Certificate	100%

Building/Wing Number I

Sr. No.	Tasks/Activity	Percentage of work done
1	Excavation	100%
2	0 number of Basement(s) and Plinth	N/A
3	0 number of Podiums	N/A
4	Stilt Floor	N/A
5	3 number of Slabs of Super Structure	100%
6	Internal walls, Internal Plaster, Floorings within Flats/Premises, Doors and Windows to each of the Flat/Premises	100%
7	Sanitary Fittings within the Flat/Premises	100%
8	Staircases, Lifts Wells and Lobbies at each Floor level connecting Staircases and Lifts, Overhead and Underground Water Tanks	100%
9	The external plumbing and external plaster, elevation, completion of terraces with waterproofing of the Building/Wing.	100%
10	Installation of lifts, water pumps, Fire Fighting Fittings and Equipment as per CFO NOC, Electrical fittings to Common Areas, electro, mechanical equipment, compliance to conditions of environment/CRZ NOC, Finishing to entrance lobby/s, plinth protection, paving of areas appurtenant to Building/Wing, Compound Wall and all other requirements as may be required to Obtain Occupation/Completion Certificate	100%



 AR CALEB FERRO
 CA | 2015 | 69608

Building/Wing Number J

Sr. No.	Tasks/Activity	Percentage of work done
1	Excavation	100%
2	0 number of Basement(s) and Plinth	N/A
3	0 number of Podiums	N/A
4	Stilt Floor	N/A
5	3 number of Slabs of Super Structure	100%
6	Internal walls, Internal Plaster, Floorings within Flats/Premises, Doors and Windows to each of the Flat/Premises	100%
7	Sanitary Fittings within the Flat/Premises	100%
8	Staircases, Lifts Wells and Lobbies at each Floor level connecting Staircases and Lifts, Overhead and Underground Water Tanks	100%
9	The external plumbing and external plaster, elevation, completion of terraces with waterproofing of the Building/Wing.	100%
10	Installation of lifts, water pumps, Fire Fighting Fittings and Equipment as per CFO NOC, Electrical fittings to Common Areas, electro, mechanical equipment, compliance to conditions of environment/CRZ NOC, Finishing to entrance lobby/s, plinth protection, paving of areas appurtenant to Building/Wing, Compound Wall and all other requirements as may be required to Obtain Occupation/Completion Certificate	100%

Building/Wing Number K

Sr. No.	Tasks/Activity	Percentage of work done
1	Excavation	100%
2	0 number of Basement(s) and Plinth	N/A
3	0 number of Podiums	N/A
4	Stilt Floor	N/A
5	3 number of Slabs of Super Structure	100%
6	Internal walls, Internal Plaster, Floorings within Flats/Premises, Doors and Windows to each of the Flat/Premises	100%
7	Sanitary Fittings within the Flat/Premises	100%
8	Staircases, Lifts Wells and Lobbies at each Floor level connecting Staircases and Lifts, Overhead and Underground Water Tanks	100%
9	The external plumbing and external plaster, elevation, completion of terraces with waterproofing of the Building/Wing.	100%
10	Installation of lifts, water pumps, Fire Fighting Fittings and Equipment as per CFO NOC, Electrical fittings to Common Areas, electro, mechanical equipment, compliance to conditions of environment/CRZ NOC, Finishing to entrance lobby/s, plinth protection, paving of areas appurtenant to Building/Wing, Compound Wall and all other requirements as may be required to Obtain Occupation/Completion Certificate	100%


 CALEB FERRO
 CA | 2015 | 69608

Building/Wing Number L

Sr. No.	Tasks/Activity	Percentage of work done
1	Excavation	100%
2	0 number of Basement(s) and Plinth	N/A
3	0 number of Podiums	N/A
4	Stilt Floor	N/A
5	3 number of Slabs of Super Structure	100%
6	Internal walls, Internal Plaster, Floorings within Flats/Premises, Doors and Windows to each of the Flat/Premises	100%
7	Sanitary Fittings within the Flat/Premises	100%
8	Staircases, Lifts Wells and Lobbies at each Floor level connecting Staircases and Lifts, Overhead and Underground Water Tanks	100%
9	The external plumbing and external plaster, elevation, completion of terraces with waterproofing of the Building/Wing.	100%
10	Installation of lifts, water pumps, Fire Fighting Fittings and Equipment as per CFO NOC, Electrical fittings to Common Areas, electro, mechanical equipment, compliance to conditions of environment/CRZ NOC, Finishing to entrance lobby/s, plinth protection, paving of areas appurtenant to Building/Wing, Compound Wall and all other requirements as may be required to Obtain Occupation/Completion Certificate	100%

Building/Wing Number M

Sr. No.	Tasks/Activity	Percentage of work done
1	Excavation	100%
2	0 number of Basement(s) and Plinth	N/A
3	0 number of Podiums	N/A
4	Stilt Floor	N/A
5	3 number of Slabs of Super Structure	100%
6	Internal walls, Internal Plaster, Floorings within Flats/Premises, Doors and Windows to each of the Flat/Premises	100%
7	Sanitary Fittings within the Flat/Premises	100%
8	Staircases, Lifts Wells and Lobbies at each Floor level connecting Staircases and Lifts, Overhead and Underground Water Tanks	100%
9	The external plumbing and external plaster, elevation, completion of terraces with waterproofing of the Building/Wing.	100%
10	Installation of lifts, water pumps, Fire Fighting Fittings and Equipment as per CFO NOC, Electrical fittings to Common Areas, electro, mechanical equipment, compliance to conditions of environment/CRZ NOC, Finishing to entrance lobby/s, plinth protection, paving of areas appurtenant to Building/Wing, Compound Wall and all other requirements as may be required to Obtain Occupation/Completion Certificate	100%


CALEB FERRO
 CA | 2015 | 69608

Building/Wing Number N

Sr. No.	Tasks/Activity	Percentage of work done
1	Excavation	100%
2	0 number of Basement(s) and Plinth	N/A
3	0 number of Podiums	N/A
4	Stilt Floor	N/A
5	3 number of Slabs of Super Structure	100%
6	Internal walls, Internal Plaster, Floorings within Flats/Premises, Doors and Windows to each of the Flat/Premises	100%
7	Sanitary Fittings within the Flat/Premises	100%
8	Staircases, Lifts Wells and Lobbies at each Floor level connecting Staircases and Lifts, Overhead and Underground Water Tanks	100%
9	The external plumbing and external plaster, elevation, completion of terraces with waterproofing of the Building/Wing.	100%
10	Installation of lifts, water pumps, Fire Fighting Fittings and Equipment as per CFO NOC, Electrical fittings to Common Areas, electro, mechanical equipment, compliance to conditions of environment/CRZ NOC, Finishing to entrance lobby/s, plinth protection, paving of areas appurtenant to Building/Wing, Compound Wall and all other requirements as may be required to Obtain Occupation/Completion Certificate	100%

Building/Wing Number O


Sr. No.	Tasks/Activity	Percentage of work done
1	Excavation	100%
2	0 number of Basement(s) and Plinth	N/A
3	0 number of Podiums	N/A
4	Stilt Floor	N/A
5	3 number of Slabs of Super Structure	100%
6	Internal walls, Internal Plaster, Floorings within Flats/Premises, Doors and Windows to each of the Flat/Premises	100%
7	Sanitary Fittings within the Flat/Premises	100%
8	Staircases, Lifts Wells and Lobbies at each Floor level connecting Staircases and Lifts, Overhead and Underground Water Tanks	100%
9	The external plumbing and external plaster, elevation, completion of terraces with waterproofing of the Building/Wing.	100%
10	Installation of lifts, water pumps, Fire Fighting Fittings and Equipment as per CFO NOC, Electrical fittings to Common Areas, electro, mechanical equipment, compliance to conditions of environment/CRZ NOC, Finishing to entrance lobby/s, plinth protection, paving of areas appurtenant to Building/Wing, Compound Wall and all other requirements as may be required to Obtain Occupation/Completion Certificate	100%

Building/Wing Number P

Sr. No.	Tasks/Activity	Percentage of work done
1	Excavation	100%
2	0 number of Basement(s) and Plinth	N/A
3	0 number of Podiums	N/A
4	Stilt Floor	N/A
5	3 number of Slabs of Super Structure	100%
6	Internal walls, Internal Plaster, Floorings within Flats/Premises, Doors and Windows to each of the Flat/Premises	100%
7	Sanitary Fittings within the Flat/Premises	100%
8	Staircases, Lifts Wells and Lobbies at each Floor level connecting Staircases and Lifts, Overhead and Underground Water Tanks	100%
9	The external plumbing and external plaster, elevation, completion of terraces with waterproofing of the Building/Wing.	100%
10	Installation of lifts, water pumps, Fire Fighting Fittings and Equipment as per CFO NOC, Electrical fittings to Common Areas, electro, mechanical equipment, compliance to conditions of environment/CRZ NOC, Finishing to entrance lobby/s, plinth protection, paving of areas appurtenant to Building/Wing, Compound Wall and all other requirements as may be required to Obtain Occupation/Completion Certificate	100%

Building/Wing Number Q

Sr. No.	Tasks/Activity	Percentage of work done
1	Excavation	100%
2	0 number of Basement(s) and Plinth	N/A
3	0 number of Podiums	N/A
4	Stilt Floor	N/A
5	3 number of Slabs of Super Structure	100%
6	Internal walls, Internal Plaster, Floorings within Flats/Premises, Doors and Windows to each of the Flat/Premises	100%
7	Sanitary Fittings within the Flat/Premises	100%
8	Staircases, Lifts Wells and Lobbies at each Floor level connecting Staircases and Lifts, Overhead and Underground Water Tanks	100%
9	The external plumbing and external plaster, elevation, completion of terraces with waterproofing of the Building/Wing.	100%
10	Installation of lifts, water pumps, Fire Fighting Fittings and Equipment as per CFO NOC, Electrical fittings to Common Areas, electro, mechanical equipment, compliance to conditions of environment/CRZ NOC, Finishing to entrance lobby/s, plinth protection, paving of areas appurtenant to Building/Wing, Compound Wall and all other requirements as may be required to Obtain Occupation/Completion Certificate	100%


 CALEB FERRO
 CA | 2015 | 69608


Building/Wing Number R

Sr. No.	Tasks/Activity	Percentage of work done
1	Excavation	100%
2	0 number of Basement(s) and Plinth	N/A
3	0 number of Podiums	N/A
4	Stilt Floor	N/A
5	3 number of Slabs of Super Structure	100%
6	Internal walls, Internal Plaster, Floorings within Flats/Premises, Doors and Windows to each of the Flat/Premises	100%
7	Sanitary Fittings within the Flat/Premises	100%
8	Staircases, Lifts Wells and Lobbies at each Floor level connecting Staircases and Lifts, Overhead and Underground Water Tanks	100%
9	The external plumbing and external plaster, elevation, completion of terraces with waterproofing of the Building/Wing.	100%
10	Installation of lifts, water pumps, Fire Fighting Fittings and Equipment as per CFO NOC, Electrical fittings to Common Areas, electro, mechanical equipment, compliance to conditions of environment/CRZ NOC, Finishing to entrance lobby/s, plinth protection, paving of areas appurtenant to Building/Wing, Compound Wall and all other requirements as may be required to Obtain Occupation/Completion Certificate	100%


TABLE-B

Internal & External Development Works in Respect of the entire Registered Phase

Sr. No.	Common areas and Facilities Amenities	Proposed (Yes/No)	Percentage of Work Done	Remarks
1	Internal Roads & Footpaths	Yes	100%	
2	Water Supply	Yes	100%	
3	Sewerage (chamber, lines, Septic Tank, STP)	Yes	100%	
4	Storm Water Drains	No	N/A	
5	Landscaping & Tree Planting	Yes	100%	
6	Street Lighting	Yes	100%	
7	Community Buildings	Yes	100%	Club House
8	Treatment and disposal of sewage and sullage water /STP	No	N/A	
9	Solid Waste Management & Disposal	No	N/A	
10	Water Conservation, Rain Water Harvesting , Percolating Well/Pit	Yes	100%	
11	Energy Management	No	N/A	
12	Fire Protection and Fire Safety Requirements	No	N/A	
13	Electrical Meter Room, Sub-station, Receiving Station	Yes	100%	
14	Firefighting facilities	No	N/A	
15	Drinking water facilities	Yes	100%	
16	Emergency evacuation services	No	N/A	
17	Use of renewable energy	No	N/A	
18	Security using CCTV surveillance	Yes	100%	
19	Letter Box	No	N/A	
20	Others (Option to Add more)			


MR CALEB FERRO
 CA | 2015 | 69608

Yours Faithfully,


AR CALEB FERRO

CA | 2015 | 69608

CALEB FERRO

Council of Architects (CoA) Registration No. CA/2015/69608

Council of Architects (CoA) Registration valid till (Date) 31/12/2026