

AN ISO 9001:2015 CERTIFIED COMPANY



ARCHITECTURE I CIVIL PROJECT CONSULTANCY AND MANAGEMENT I INTERIOR DESIGN I STRUCTURAL DESIGN

FORM 1


ARCHITECT'S CERTIFICATE

(To be submitted at the time of Registration of Ongoing Project and for withdrawal of Money from Designated Account)

Date: 1.10.2019

SID(

To
M/S.SAVANI CORPORATION,
PRAYOSHA PRIME,
F.P.NO.10, O.P. SURVEY.NO. 135,
SUB PLOT NO. 2/2A,
DINDOLI KARADAVA ROAD, DINDOLI,
SURAT—394210.



Subject: Certificate of Percentage of Completion of Construction Work of 6 No. of Building(s) A1,A2 + A3,A4 + A5 + B1,B2,B3 + B4,B5,B6 + B7 Wing(s) of the 1st Phase of the Project (Gujarat RERA Registration Number: PR/GJ/SURAT/CHORASI/SUDA/MAA05674/090719) situated on the Plot bearing T.P.S.NO:62 (DINDOLI -BHESTAN-BHEDVAD), Block No:246, F.P.No:51, O.P.No:51, Sub Plot No. 1 & 2 demarcated by its boundaries 21.145180, 72.867316 to the North and 21.144777, 72. 867409 to the South, 21.144977, 72.867700 to the East, 21.144950, 72.867021 to the West, Village: Dindoli, District: Surat, PIN:394210 admeasuring 7042.00 sq.mts. area being developed by M/S Savani Corporation.

Sir,

I, Manan Prashantbhai Sheth, have undertaken assignment as Architect/Engineer of certifying Percentage of Completion of Construction Work of 6 No. of Building(s) A1,A2 + A3,A4 + A5 + B1,B2,B3 + B4,B5,B6 + B7 Wing(s) of the 1st Phase of the Project (Gujarat RERA Registration Number: PR/GJ/SURAT/CHORASI/SUDA/MAA05674/090719) situated on the Plot bearing T.P.S.NO:62 (DINDOLI -BHESTAN-BHEDVAD), Block No:246, F.P.No:51, O.P.No:51, Sub plot No.-1&2, Moje: Dindoli, District: Surat, PIN:394210 admeasuring 7042.00 sq.mts. area being developed by M/S Savani Corporation.

- 1. Following technical professionals are appointed by Owner/Promoter:- (as applicable)
 - (i) M/s./Shri/Smt. Kantilal G. Patel as Engineer
 - (ii) M/s./Shri/Smt. Amit K. Shah as Structural Consultant
 - (iii) M/s./Shri/Smt. has not appointed as MEP Consultant
 - (iv) M/s./Shri/Smt. Kantilal G. Patel as Site Supervisor/Clerk of Works

Based on Site Inspection on 30.09.2019, with respect to each of the Building/Wing of the aforesaid Real Estate Project, I certify that as on the date of this certificate, the Percentage of Work done for each of the building/Wing of the Real Estate Project as registered vide number Applied For Registration under GujRERA is as per table A herein below. The percentage of the work executed with respect to each of the activity of the entire phase is detailed in Table A and B.







Table - A

Building: 1, Wing Number A1,A2,

Sr. No.	Tasks/Activity	Percentage of work done	
1	Excavation	100%	
2	1 number of Basement(s) and Plinth	5%	
3	0 number of Podiums	NA	
4	Stilt Floor	NA	
5	9 number of Slabs of Super Structure	10%	
6	Internal walls, Internal Plaster, Floorings within Flats/Premises, Doors and Windows to each of the Flat/Premises	0%	
7	Sanitary Fittings within the Flat/Premises	0%	
8	Staircases, Lifts Wells and Lobbies at each Floor level connecting Staircases and Lifts, Overhead and Underground Water Tanks	0%	
9	The external plumbing and external plaster, elevation, completion of terraces with waterproofing of the Building/Wing.	0%	
10	Installation of lifts, water pumps, Fire Fighting Fittings and Equipment as per CFO NOC, Electrical fittings to Common Areas, electro, mechanical equipment, compliance to conditions of environment/CRZ NOC, Finishing to entrance lobby/s, plinth protection, paving of areas appurtenant to Building/Wing, Compound Wall and all other requirements as may be required to Obtain Occupation/Completion Certificate		





Table - A

Building: 2, Wing Number A3,A4

Sr. No.	Tasks/Activity	Percentage of work done	
1	Excavation	100%	
2	1 number of Basement(s) and Plinth	30%	
3	0 number of Podiums	NA	
4	Stilt Floor	0%	
5	9 number of Slabs of Super Structure	10%	
6	Internal walls, Internal Plaster, Floorings within Flats/Premises, Doors and Windows to each of the Flat/Premises	0%	
7	Sanitary Fittings within the Flat/Premises	0%	
8	Staircases, Lifts Wells and Lobbies at each Floor level connecting Staircases and Lifts, Overhead and Underground Water Tanks	0%	
9	The external plumbing and external plaster, elevation, completion of terraces with waterproofing of the Building/Wing.	0%	
10	Installation of lifts, water pumps, Fire Fighting Fittings and Equipment as per CFO NOC, Electrical fittings to Common Areas, electro, mechanical equipment, compliance to conditions of environment/CRZ NOC, Finishing to entrance lobby/s, plinth protection, paving of areas appurtenant to Building/Wing, Compound Wall and all other requirements as may be required to Obtain Occupation/Completion Certificate	0%	









Table - A

Building: 3, Wing Number A5

Sr. No.	Tasks/Activity	Percentage of work done	
1	Excavation	100%	
2	1 number of Basement(s) and Plinth	30%	
3	0 number of Podiums	NA	
4	Stilt Floor	0%	
5	9 number of Slabs of Super Structure	20%	
6	Internal walls, Internal Plaster, Floorings within Flats/Premises, Doors and Windows to each of the Flat/Premises	0%	
7	Sanitary Fittings within the Flat/Premises	0%	
8	Staircases, Lifts Wells and Lobbies at each Floor level connecting Staircases and Lifts, Overhead and Underground Water Tanks	0%	
9	The external plumbing and external plaster, elevation, completion of terraces with waterproofing of the Building/Wing.	0%	
10	Installation of lifts, water pumps, Fire Fighting Fittings and Equipment as per CFO NOC, Electrical fittings to Common Areas, electro, mechanical equipment, compliance to conditions of environment/CRZ NOC, Finishing to entrance lobby/s, plinth protection, paving of areas appurtenant to Building/Wing, Compound Wall and all other requirements as may be required to Obtain Occupation/Completion Certificate	0%	









Table - A

Building: 4, Wing Number B1,B2,B3

Sr. No.	Tasks/Activity	Percentage of work done	
1	Excavation	100%	
2	1 number of Basement(s) and Plinth	30%	
3	0 number of Podiums	NA	
4	Stilt Floor	0%	
5	9 number of Slabs of Super Structure	5%	
6	Internal walls, Internal Plaster, Floorings within Flats/Premises, Doors and Windows to each of the Flat/Premises	0%	
7	Sanitary Fittings within the Flat/Premises	0%	
8	Staircases, Lifts Wells and Lobbies at each Floor level connecting Staircases and Lifts, Overhead and Underground Water Tanks	0%	
9	The external plumbing and external plaster, elevation, completion of terraces with waterproofing of the Building/Wing.	0%	
10	Installation of lifts, water pumps, Fire Fighting Fittings and Equipment as per CFO NOC, Electrical fittings to Common Areas, electro, mechanical equipment, compliance to conditions of environment/CRZ NOC, Finishing to entrance lobby/s, plinth protection, paving of areas appurtenant to Building/Wing, Compound Wall and all other requirements as may be required to Obtain Occupation/Completion Certificate		









Table - A

Building: 5, Wing Number B4, B5, B6

Sr. No.	Tasks/Activity	Percentage of work done	
1	Excavation	0%	
2	1 number of Basement(s) and Plinth	0%	
3	0 number of Podiums	NA	
4	Stilt Floor	0%	
5	9 number of Slabs of Super Structure	0%	
6	Internal walls, Internal Plaster, Floorings within Flats/Premises, Doors and Windows to each of the Flat/Premises	0%	
7	Sanitary Fittings within the Flat/Premises	0%	
8	Staircases, Lifts Wells and Lobbies at each Floor level connecting Staircases and Lifts, Overhead and Underground Water Tanks	0%	
9	The external plumbing and external plaster, elevation, completion of terraces with waterproofing of the Building/Wing.	0%	
10	Installation of lifts, water pumps, Fire Fighting Fittings and Equipment as per CFO NOC, Electrical fittings to Common Areas, electro, mechanical equipment, compliance to conditions of environment/CRZ NOC, Finishing to entrance lobby/s, plinth protection, paving of areas appurtenant to Building/Wing, Compound Wall and all other requirements as may be required to Obtain Occupation/Completion Certificate		









Table - A

Building: 6, Wing Number B7

Sr. No.	Tasks/Activity	Percentage of work done	
1	Excavation	100%	
2	1 number of Basement(s) and Plinth	15%	
3	0 number of Podiums	NA	
4	Stilt Floor	0%	
5	9 number of Slabs of Super Structure	0%	
6	Internal walls, Internal Plaster, Floorings within Flats/Premises, Doors and Windows to each of the Flat/Premises	0%	
7	Sanitary Fittings within the Flat/Premises	0%	
8	Staircases, Lifts Wells and Lobbies at each Floor level connecting Staircases and Lifts, Overhead and Underground Water Tanks	0%	
9	The external plumbing and external plaster, elevation, completion of terraces with waterproofing of the Building/Wing.	0%	
10	Installation of lifts, water pumps, Fire Fighting Fittings and Equipment as per CFO NOC, Electrical fittings to Common Areas, electro, mechanical equipment, compliance to conditions of environment/CRZ NOC, Finishing to entrance lobby/s, plinth protection, paving of areas appurtenant to Building/Wing, Compound Wall and all other requirements as may be required to Obtain Occupation/Completion Certificate		





TABLE-B Internal & External Development Works in Respect of the entire Registered Phase

Sr. No.	Common areas and Facilities Amenities	Proposed (Yes/No)	Percentage of Work Done	Remarks
1	Internal Roads & Footpaths	Yes	0%	
2	Water Supply	Yes	0%	
3	Sewerage (chamber, lines, Septic Tank, STP)	Yes	0%	
4	Storm Water Drains	Yes	0%	
5	Landscaping & Tree Planting	Yes	0%	
6	Street Lighting	Yes	0%	
7	Community Buildings	No	NA	
8	Treatment and disposal of sewage and sullage water /STP	No	NA	
9	Solid Waste Management & Disposal	No	NA	
10	Water Conservation, Rain Water Harvesting , Percolating Well/Pit	Yes	0%	
11	Energy Management	No	NA	
12	Fire Protection and Fire Safety Requirements	Yes	0%	
13	Electrical Meter Room, Sub-station, Receiving Station	Yes	0%	
14	Others (Option to Add more)	No	NA	

Yours Faithfully,

MANAN PRASHATBHAI SHETH

Council of Architects (COA) Registration No. CA/2010/47939 Council of Architects (COA) Registration valid till 31.12.2022

SMC License No: TDO/AR/224

