# Harsh Pandya & Associates

+91 78749 60606

2

harshpandya011@gmail.com



218-19, Lakulesh Avenue, Delux Square, Nizampura, Vadodara.

ø

#### FORM 1

#### ARCHITECT'S CERTIFICATE

To be submitted at the time of Registration of Ongoing Project and for withdrawal of Money from Designated Account)

Date: 31/12/2019

To

Guruprasad Infrastructrue Pvt. Ltd. Opp. JiJimata Mandir, Makarpura main road. Baroda-390013

Subject: Certificate of Percentage of Completion of Construction Work of SHIVABHI LUXURIA No. of Building(s) 22 Wing(s) of the final Phase of the Project (Gujarat RERA Registration Number) situated on the Plot bearing C.N. No/CTS No/Survey no/Final Plot no 41 & 548/2 being latitude at 22 degrees & longitude at 73 degrees towards Naliya road to the North, Plot No: 548/1 to the South, N.H. No. 08 to the East, R.S. no. 552 to the west of Division Makarpura & Jambua village, Vadodara District PIN 390013 admeasuring 28115.79 sq.mts. area being developed by Guruprasad

Sir

I/We Harsh Pandya & Associates have undertaken assignment as Architect/Engineer of certifying Percentage of Completion of Construction Work of the 22 Building(s) of the final Phase of the Project, situated on the plot bearing C.N. No./CTS No./Survey no./Final Plot no. 41 & 548/2 of Division Makarpura & Jambua, Vadodara District PIN 390013 admeasuring 28115.79 sq.mts. area being developed by Guruprasad Infrastructure Pvt. Ltd. as

- 1. Following technical professionals are appointed by Owner/Promoter:- (as applicable)
  - (i) M/s/Shri/Smt. Harsh Pandya & Associates as Architect.
  - (ii) M/s /Shri/Smt. Swati Associates as Structural Consultant
  - (iii) M/s./Shri/Smt. as MEP Consultant
  - (iv) M/s./Shri/Smt. Amit C Patel as Site Supervisor/Clerk of Works

Based on Site Inspection, with respect to each of the Building/Wing of the aforesaid Real Estate Project, I certify that as on the date of this certificate, the Percentage of Work done for each of the building/Wing of the Real Estate Project as registered vide number RAA04073/191118 under GujRERA is as per table A herein below. The percentage of the work executed with respect to each of the activity of the entire phase is detailed in Table A and B.

Table – A

Building/Wing Number E (to be prepared separately for each Building/Wing of the Project)

Sr. No	Tasks/Activity	Percentage of work
2	Excavation	75.000
_	1 number of Plinth	100%
3	0 number of Podiums	100%
4	Stilt Floor	
5	6 number of Slabs of Super Structure	100%
		100%
6	Internal walls, Internal Plaster, Floorings within Flats/Premises, Doors and Windows to each of the Flat/Premises	
7	Sanitary Fittings within the Flat/Premises	100%
		100%
8	Staircases, Lifts Wells and Lobbies at each Floor level connecting Staircases and Lifts, Overhead and Underground Water Tanks	
45	The external olymbian and automatical in the control of the contro	100%
9	The external plumbing and external plaster, elevation, completion of terraces with waterproofing of the Building/Wing	
		100%
10	Installation of lifts, water pumps, Fire Fighting Fittings and Equipment as per CFO NOC, Electrical fittings to Common Areas, electro, mechanical equipment, compliance to conditions of environment/CRZ NOC, Finishing to entrance lobby/s, plinth protection, paving of areas appurtenant to Building/Wing, Compound Wall and all other requirements as may be required to Obtain Occupation/Completion Certificate	
		100%

HARSH P. PANDYA (ARCHITECT)

HARSH PANDYA & ASSOCIATES 218-19, 2nd Floor, Lakulesh Avenue,

Delux Square, Nizampura, Vadodara.
VMC Lic. No.: Vuda Lic No.:

June Marie S

# $Building/Wing\ Number\ \textbf{\textit{F}}\ \ (to\ be\ prepared\ separately\ for\ each\ Building/Wing\ of\ the\ Project)$

Sr. No	Tasks/Activity  Excavation	Percentage of work
2		100%
	1 number of Plinth	100%
3	0 number of Podiums	100%
4	Stilt Floor	
5	6 number of Slabs of Super Structure	100%
6	Internal walls, Internal Plaster, Floorings within Flats/Premises, Doors and Windows to each of the Flat/Premises	100%
7	Sanitary Fittings within the Flat/Premises	100%
8	Staircases, Lifts Wells and Lobbies at each Floor level connecting Staircases and Lifts, Overhead and Underground Water Tanks	100%
9	The external plumbing and external plaster, elevation, completion of terraces with waterproofing of the Building/Wing	100%
	Installation of lifts, water pumps, Fire Fighting Fittings and Equipment as per CFO NOC, Electrical fittings to Common Areas, electro, mechanical equipment, compliance to conditions of environment/CRZ NOC, Finishing to entrance lobby/s, plinth protection, paving of areas appurtenant to Building/Wing, Compound Wall and all other requirements as may be required to Obtain Occupation/Completion Certificate	100%

# $Building/Wing\ Number\ \ \textbf{G}\ (to\ be\ prepared\ separately\ for\ each\ Building/Wing\ of\ the\ Project)$

Sr. No	Tasks/Activity	Percentage of work done
1	Excavation	
2	1 number of Plinth	100%
3	0 number of Podiums	100%
4	Stilt Floor	
5	6 number of Slabs of Super Structure	100%
6	Internal walls, Internal Plaster, Floorings within Flats/Premises, Doors and Windows to each of the Flat/Premises	100%
7	Sanitary Fittings within the Flat/Premises	50%
8	Staircases, Lifts Wells and Lobbies at each Floor level connecting Staircases and Lifts, Overhead and Underground Water Tanks	0%
9	The external plumbing and external plaster, elevation, completion of terraces with waterproofing of the Building/Wing	0%
10	Installation of lifts, water pumps, Fire Fighting Fittings and Equipment as per CFO NOC, Electrical fittings to Common Areas, electro, mechanical equipment, compliance to conditions of environment/CRZ NOC, Finishing to entrance lobby/s, plinth protection, paving of areas appurtenant to Building/Wing, Compound Wall and all other requirements as may be required to Obtain Occupation/Completion Certificate	0%
	other requirements as may be required to Obtain Occupation/Completion Certificate	

# Building/Wing Number H (to be prepared separately for each Building/Wing of the Project)

Sr. No	Tasks/Activity	Percentage of work done
1	Excavation	100%
2	1 number of Plinth	
3	0 number of Podiums	100%
4	Stilt Floor	
5	6 number of Slabs of Super Structure	100%
11 - F		100%
6	Internal walls, Internal Plaster, Floorings within Flats/Premises, Doors and Windows to each of the Flat/Premises	100%
7	Sanitary Fittings within the Flat/Premises	100%
8	Staircases, Lifts Wells and Lobbies at each Floor level connecting Staircases and Lifts, Overhead and Underground Water Tanks	100%
	The external plumbing and external places; elevation and latin C.	100%
9	The external plumbing and external plaster, elevation, completion of terraces with waterproofing of the Building/Wing	100%
10	Installation of lifts, water pumps, Fire Fighting Fittings and Equipment as per CFO NOC, Electrical fittings to Common Areas, electro, mechanical equipment, compliance to conditions of environment/CRZ NOC, Finishing to entrance lobby/s, plinth protection, paving of areas appurtenant to Building/Wing, Compound Wall and all other requirements as may be required to Obtain Occupation/Completion Certificate	100%
		100%

# $Building/Wing\ Number\ \textbf{I}\ \ \text{(to be prepared separately for each Building/Wing of the Project)}$

Sr. No	Tasks/Activity	Percentage of work
1	Excavation	done
2	1 number of Plinth	100%
3	0 number of Podiums	100%
4	Stilt Floor	
5	6 number of Slabs of Super Structure	100%
6	Internal walls, Internal Plaster, Floorings within Flats/Premises, Doors and Windows to each of the Flat/Premises	100%
7	Sanitary Fittings within the Flat/Premises	100%
8	Staircases, Lifts Wells and Lobbies at each Floor level connecting Staircases and Lifts, Overhead and Underground Water Tanks	100%
		100%

HARSH P. PANDYA
(ARCHITECT)

HARSH PANDYA & ASSOCIATES
218-19, 2nd Floor, Lakulesh Avenue,
Delux Square, Nizampura, Vadodara.
VMC Lic. No.: Vuda Lic No.:

100% 100% 100% 100%

9	The external plumbing and external plaster, elevation, completion of terraces with waterproofing of the Building/Wing	
		100%
10	Installation of lifts, water pumps, Fire Fighting Fittings and Equipment as per CFO NOC, Electrical fittings to Common Areas, electro, mechanical equipment, compliance to conditions of environment/CRZ NOC, Finishing to entrance lobby/s, plinth protection, paving of areas appurtenant to Building/Wing, Compound Wall and all other requirements as may be required to Obtain Occupation/Completion Certificate	
		100%

## Building/Wing Number J (to be prepared separately for each Building/Wing of the Project)

Sr. No	Tasks/Activity	Percentage of work done
1	Excavation	100%
2	1 number of Plinth	100%
3	0 number of Podiums	10076
4	Stilt Floor	100%
5	6 number of Slabs of Super Structure	100%
6	Internal walls, Internal Plaster, Floorings within Flats/Premises, Doors and Windows to each of the Flat/Premises	50%
7	Sanitary Fittings within the Flat/Premises	0%
8	Staircases, Lifts Wells and Lobbies at each Floor level connecting Staircases and Lifts, Overhead and Underground Water Tanks	
9	The external plumbing and external plaster, elevation, completion of terraces with waterproofing of the Building/Wing	0%
	Installation of lifts, water pumps, Fire Fighting Fittings and Equipment as per CFO NOC, Electrical fittings to Common Areas, electro, mechanical equipment, compliance to conditions of environment/CRZ NOC, Finishing to entrance lobby/s, plinth protection, paving of areas appurtenant to Building/Wing, Compound Wall and all other requirements as may be required to Obtain Occupation/Completion Certificate	
_		0%

## Building/Wing Number K (to be prepared separately for each Building/Wing of the Project)

Sr. No	Tasks/Activity	Percentage of work done
1	Excavation	100%
2	1 number of Plinth	100%
3	0 number of Podiums	100%
4	Stilt Floor	100%
5	6 number of Slabs of Super Structure	100%
6	Internal walls, Internal Plaster, Floorings within Flats/Premises, Doors and Windows to each of the Flat/Premises	75%
7	Sanitary Fittings within the Flat/Premises	75%
8	Staircases, Lifts Wells and Lobbies at each Floor level connecting Staircases and Lifts, Overhead and Underground Water Tanks	
	The external plumbing and external place at the second sec	75%
9	The external plumbing and external plaster, elevation, completion of terraces with waterproofing of the Building/Wing	75%
10	Installation of lifts, water pumps, Fire Fighting Fittings and Equipment as per CFO NOC, Electrical fittings to Common Areas, electro, mechanical equipment, compliance to conditions of environment/CRZ NOC, Finishing to entrance lobby/s, plinth protection, paving of areas appurtenant to Building/Wing, Compound Wall and all other requirements as may be required to Obtain Occupation/Completion Certificate	
		75%

## Building/Wing Number ${f L}$ (to be prepared separately for each Building/Wing of the Project)


Sr. No	Tasks/Activity	Percentage of work done
1	Excavation	100%
2	1 number of Plinth	100%
3	0 number of Podiums	10076
4	Stilt Floor	100%
5	6 number of Slabs of Super Structure	100%
6	Internal walls, Internal Plaster, Floorings within Flats/Premises, Doors and Windows to each of the Flat/Premises	100%
7	Sanitary Fittings within the Flat/Premises	100%
8	Staircases, Lifts Wells and Lobbies at each Floor level connecting Staircases and Lifts, Overhead and Underground Water Tanks	
	The external alumbing and external alumbing alumbing and external alumbing and external alumbing and external	100%
9	The external plumbing and external plaster, elevation, completion of terraces with waterproofing of the Building/Wing	100%
10	Installation of lifts, water pumps, Fire Fighting Fittings and Equipment as per CFO NOC, Electrical fittings to Common Areas, electro, mechanical equipment, compliance to conditions of environment/CRZ NOC, Finishing to entrance lobby/s, plinth protection, paving of areas appurtenant to Building/Wing, Compound Wall and all other requirements as may be required to Obtain Occupation/Completion Certificate	
		100%

# $Building/Wing\ Number\ \textbf{M}\ \ (to\ be\ prepared\ separately\ for\ each\ Building/Wing\ of\ the\ Project)$

Sr. No	Tasks/Activity	Percentage of work done
1	Excavation	
2	1 number of Plinth	100%
3	0 number of Podiums	100%
4	Stilt Floor	100%
		100

HARSH P. PANDYA
(ARCHITECT)

HARSH PANDYA & ASSOCIATES
218-19, 2nd Floor, Lakulesh Avenue,
Delux Square, Nizampura, Vadodara.
VMC Lic. No.: Vuda Lic No.:



5	6 number of Slabs of Super Structure	100%
6	Internal walls, Internal Plaster, Floorings within Flats/Premises, Doors and Windows to each of the Flat/Premises	100%
7	Sanitary Fittings within the Flat/Premises	100%
8	Staircases, Lifts Wells and Lobbies at each Floor level connecting Staircases and Lifts, Overhead and Underground Water Tanks	100%
9	The external plumbing and external plaster, elevation, completion of terraces with waterproofing of the Building/Wing	100%
10	Installation of lifts, water pumps, Fire Fighting Fittings and Equipment as per CFO NOC, Electrical fittings to Common Areas, electro, mechanical equipment, compliance to conditions of environment/CRZ NOC, Finishing to entrance lobby/s, plinth protection, paving of areas appurtenant to Building/Wing, Compound Wall and all other requirements as may be required to Obtain Occupation/Completion Certificate	1000/
		100%

#### $Building/Wing\ Number\ {\pmb N}\ \ \ (\text{to be prepared separately for each Building/Wing of the Project)}$

Sr. No	Tasks/Activity	Percentage of work done
1	Excavation	100%
2	1 number of Plinth	100%
3	0 number of Podiums	
4	Stilt Floor	100%
5	6 number of Slabs of Super Structure	100%
6	Internal walls, Internal Plaster, Floorings within Flats/Premises, Doors and Windows to each of the Flat/Premises	100%
7	Sanitary Fittings within the Flat/Premises	100%
8	Staircases, Lifts Wells and Lobbies at each Floor level connecting Staircases and Lifts, Overhead and Underground Water Tanks	100%
9	The external plumbing and external plaster, elevation, completion of terraces with waterproofing of the Building/Wing	100%
10	Installation of lifts, water pumps, Fire Fighting Fittings and Equipment as per CFO NOC, Electrical fittings to Common Areas, electro, mechanical equipment, compliance to conditions of environment/CRZ NOC, Finishing to entrance lobby/s, plinth protection, paving of areas appurtenant to Building/Wing, Compound Wall and all other requirements as may be required to Obtain Occupation/Completion Certificate	100%

#### Building/Wing Number O (to be prepared separately for each Building/Wing of the Project)

Sr. No	Tasks/Activity	Percentage of work done
1	Excavation	100%
2	1 number of Plinth	100%
3	0 number of Podiums	
4	Stilt Floor	100%
5	6 number of Slabs of Super Structure	100%
6	Internal walls, Internal Plaster, Floorings within Flats/Premises, Doors and Windows to each of the Flat/Premises	100%
7	Sanitary Fittings within the Flat/Premises	100%
8	Staircases, Lifts Wells and Lobbies at each Floor level connecting Staircases and Lifts, Overhead and Underground Water Tanks	100%
9	The external plumbing and external plaster, elevation, completion of terraces with waterproofing of the Building/Wing	100%
10	Installation of lifts, water pumps, Fire Fighting Fittings and Equipment as per CFO NOC, Electrical fittings to Common Areas, electro, mechanical equipment, compliance to conditions of environment/CRZ NOC, Finishing to entrance lobby/s, plinth protection, paving of areas appurtenant to Building/Wing, Compound Wall and all other requirements as may be required to Obtain Occupation/Completion Certificate	100%

#### $Building/Wing\ Number\ \textbf{P}\ \ (\text{to be prepared separately for each Building/Wing of the Project)}$

Sr. No	Tasks/Activity	Percentage of work done	
1	Excavation	100%	
2	1 number of Plinth	100%	
3	0 number of Podiums		HARSH P.
4	Stilt Floor	100%	(ARC
5	6 number of Slabs of Super Structure	100%	
6	Internal walls, Internal Plaster, Floorings within Flats/Premises, Doors and Windows to each of the Flat/Premises	100%	HARSH PANDYA
7	Sanitary Fittings within the Flat/Premises	100%	218-19, 2nd Floor,
8	Staircases, Lifts Wells and Lobbies at each Floor level connecting Staircases and Lifts, Overhead and Underground Water Tanks	100%	Delux Square, Niza VMC Lic. No.:
9	The external plumbing and external plaster, elevation, completion of terraces with waterproofing of the Building/Wing	100%	10
10	Installation of lifts, water pumps, Fire Fighting Fittings and Equipment as per CFO NOC, Electrical fittings to Common Areas, electro, mechanical equipment, compliance to conditions of environment/CRZ NOC, Finishing to entrance lobby/s, plinth protection, paving of areas appurtenant to Building/Wing, Compound Wall and all other requirements as may be required to Obtain Occupation/Completion Certificate	100%	Mary
	Building/Wing Number <b>Q</b> (to be prepared separately for each Building/Wing of the Project)	1	July 8

HARSH P. PANDYA (ARCHITECT) HARSH PANDYA & ASSOCIATES 218-19, 2nd Floor, Lakulesh Avenue, Delux Square, Nizampura, Vadodara VMC Lic. No.: Vuda Lic No.:

Sr. No	Tasks/Activity	Percentage of work done
1	Excavation	100%
2	1 number of Plinth	100%
3	0 number of Podiums	10076
4	Stilt Floor	100%
5	6 number of Slabs of Super Structure	100%
6	Internal walls, Internal Plaster, Floorings within Flats/Premises, Doors and Windows to each of the Flat/Premises	100%
7	Sanitary Fittings within the Flat/Premises	100%
8	Staircases, Lifts Wells and Lobbies at each Floor level connecting Staircases and Lifts, Overhead and Underground Water Tanks	
9	The external plumbing and external plaster, elevation, completion of terraces with waterproofing of the Building/Wing	100%
10	Installation of lifts, water pumps, Fire Fighting Fittings and Equipment as per CFO NOC, Electrical fittings to Common Areas, electro, mechanical equipment, compliance to conditions of environment/CRZ NOC, Finishing to entrance lobby/s, plinth protection, paving of areas appurtenant to Building/Wing, Compound Wall and all other requirements as may be required to Obtain Occupation/Completion Certificate	
		100%

# $Building/Wing\ Number\ \textbf{R}\ (to\ be\ prepared\ separately\ for\ each\ Building/Wing\ of\ the\ Project)$

Sr. No	Tasks/Activity	Percentage of work done
1	Excavation	100%
2	1 number of Plinth	100%
3	0 number of Podiums	10070
4	Stilt Floor	100%
5	6 number of Slabs of Super Structure	100%
	Internal walls, Internal Plaster, Floorings within Flats/Premises, Doors and Windows to each of the Flat/Premises	100%
7	Sanitary Fittings within the Flat/Premises	100%
8	Staircases, Lifts Wells and Lobbies at each Floor level connecting Staircases and Lifts, Overhead and Underground Water Tanks	100%
9	The external plumbing and external plaster, elevation, completion of terraces with waterproofing of the Building/Wing	100%
10	Installation of lifts, water pumps, Fire Fighting Fittings and Equipment as per CFO NOC, Electrical fittings to Common Areas, electro, mechanical equipment, compliance to conditions of environment/CRZ NOC, Finishing to entrance lobby/s, plinth protection, paving of areas appurtenant to Building/Wing, Compound Wall and all other requirements as may be required to Obtain Occupation/Completion Certificate	100%

## Building/Wing Number \$ (to be prepared separately for each Building/Wing of the Project)

Sr. No	Tasks/Activity	Percentage of work done
1	Excavation	100%
2	1 number of Plinth	100%
3	0 number of Podiums	100/0
4	Stilt Floor	100%
5	6 number of Slabs of Super Structure	100%
6	Internal walls, Internal Plaster, Floorings within Flats/Premises, Doors and Windows to each of the Flat/Premises	100%
7	Sanitary Fittings within the Flat/Premises	100%
8	Staircases, Lifts Wells and Lobbies at each Floor level connecting Staircases and Lifts, Overhead and Underground Water Tanks	100%
9	The external plumbing and external plaster, elevation, completion of terraces with waterproofing of the Building/Wing	100%
	Installation of lifts, water pumps, Fire Fighting Fittings and Equipment as per CFO NOC, Electrical fittings to Common Areas, electro, mechanical equipment, compliance to conditions of environment/CRZ NOC, Finishing to entrance lobby/s, plinth protection, paving of areas appurtenant to Building/Wing, Compound Wall and all other requirements as may be required to Obtain Occupation/Completion Certificate	100%

# $Building/Wing\ Number\ \ \textbf{T}\ (to\ be\ prepared\ separately\ for\ each\ Building/Wing\ of\ the\ Project)$

Sr. No	Tasks/Activity	Percentage of work done
1	Excavation	1009
2	1 number of Plinth	100%
3	0 number of Podiums	1007
4	Stilt Floor	1009
5	6 number of Slabs of Super Structure	1009
6	Internal walls, Internal Plaster, Floorings within Flats/Premises, Doors and Windows to each of the Flat/Premises	100
7	Sanitary Fittings within the Flat/Premises	1009
8	Staircases, Lifts Wells and Lobbies at each Floor level connecting Staircases and Lifts, Overhead and Underground Water Tanks	1009
9	The external plumbing and external plaster, elevation, completion of terraces with waterproofing of the Building/Wing	100

HARSH P. PANDYA (ARCHITECT)

10	Installation of lifts, water pumps, Fire Fighting Fittings and Equipment as per CFO NOC, Electrical fittings to Common Areas, electro, mechanical equipment, compliance to conditions of environment/CRZ NOC, Finishing to entrance lobby/s, plinth protection, paving of areas appurtenant to Building/Wing, Compound Wall and all other requirements as may be required to Obtain Occupation/Completion Certificate	100
----	---	-----

# 

Sr. No	Tasks/Activity	Percentage of work done
1	Excavation	100%
2	1 number of Plinth	100%
3	0 number of Podiums	
4	Stilt Floor	100%
5	6 number of Slabs of Super Structure	100%
6	Internal walls, Internal Plaster, Floorings within Flats/Premises, Doors and Windows to each of the Flat/Premises	100%
7	Sanitary Fittings within the Flat/Premises	100%
8	Staircases, Lifts Wells and Lobbies at each Floor level connecting Staircases and Lifts, Overhead and Underground Water Tanks	100%
9	The external plumbing and external plaster, elevation, completion of terraces with waterproofing of the Building/Wing	100%
10	Installation of lifts, water pumps, Fire Fighting Fittings and Equipment as per CFO NOC, Electrical fittings to Common Areas, electro, mechanical equipment, compliance to conditions of environment/CRZ NOC, Finishing to entrance lobby/s, plinth protection, paving of areas appurtenant to Building/Wing, Compound Wall and all other requirements as may be required to Obtain Occupation/Completion Certificate	100%

# Building/Wing Number $\, {f V} \,$ (to be prepared separately for each Building/Wing of the Project)

Sr. No	Tasks/Activity	Percentage of work done
1	Excavation	100%
2	1 number of Plinth	100%
3	0 number of Podiums	1007
4	Stilt Floor	100%
5	6 number of Slabs of Super Structure	100%
6	Internal walls, Internal Plaster, Floorings within Flats/Premises, Doors and Windows to each of the Flat/Premises	100%
7	Sanitary Fittings within the Flat/Premises	90%
8	Staircases, Lifts Wells and Lobbies at each Floor level connecting Staircases and Lifts, Overhead and Underground Water Tanks	90%
9	The external plumbing and external plaster, elevation, completion of terraces with waterproofing of the Building/Wing	95%
10	Installation of lifts, water pumps, Fire Fighting Fittings and Equipment as per CFO NOC, Electrical fittings to Common Areas, electro, mechanical equipment, compliance to conditions of environment/CRZ NOC, Finishing to entrance lobby/s, plinth protection, paving of areas appurtenant to Building/Wing, Compound Wall and all other requirements as may be required to Obtain Occupation/Completion Certificate	90%

#### Building/Wing Number W (to be prepared separately for each Building/Wing of the Project)

Sr. No	Tasks/Activity	Percentage of work done
1	Excavation	100%
2	1 number of Plinth	100%
3	0 number of Podiums	
4	Stilt Floor	100%
5	6 number of Slabs of Super Structure	100%
6	Internal walls, Internal Plaster, Floorings within Flats/Premises, Doors and Windows to each of the Flat/Premises	100%
7	Sanitary Fittings within the Flat/Premises	100%
8	Staircases, Lifts Wells and Lobbies at each Floor level connecting Staircases and Lifts, Overhead and Underground Water Tanks	100%
9	The external plumbing and external plaster, elevation, completion of terraces with waterproofing of the Building/Wing	100%
10	Installation of lifts, water pumps, Fire Fighting Fittings and Equipment as per CFO NOC, Electrical fittings to Common Areas, electro, mechanical equipment, compliance to conditions of environment/CRZ NOC, Finishing to entrance lobby/s, plinth protection, paving of areas appurtenant to Building/Wing, Compound Wall and all other requirements as may be required to Obtain Occupation/Completion Certificate	100%

 $Building/Wing\ Number\ \ \textbf{X}\ (to\ be\ prepared\ separately\ for\ each\ Building/Wing\ of\ the\ Project)$ 

Sr. No	Tasks/Activity	Percentage of work done
1	Excavation	100%
2	1 number of Plinth	100%
3	0 number of Podiums	10076
4	Stilt Floor	100%
5	6 number of Slabs of Super Structure	100%

HARSH P. PANDYA
(ARCHITECT)

HARSH PANDYA & ASSOCIATES
218-19, 2nd Floor, Lakulesh Avenue,
1000%
Delux Square, Nizampura, Vadodara.
VMC Lic. No.:
Vuda Lic No.:

10% 00% 00% 00% 00% 00%

6	Internal walls, Internal Plaster, Floorings within Flats/Premises, Doors and Windows to each of the Flat/Premises	
7	Sanitary Fittings within the Flat/Premises	100%
8	Staircases, Lifts Wells and Lobbies at each Floor level connecting Staircases and Lifts, Overhead and Underground Water Tanks	100%
9	The external plumbing and external plaster, elevation, completion of terraces with waterproofing of the Building/Wing	100%
10	Installation of lifts, water pumps, Fire Fighting Fittings and Equipment as per CFO NOC, Electrical fittings to Common Areas, electro, mechanical equipment, compliance to conditions of environment/CRZ NOC, Finishing to entrance lobby/s, plinth protection, paving of areas appurtenant to Building/Wing, Compound Wall and all other requirements as may be required to Obtain Occupation/Completion Certificate	
		100%

## Building/Wing Number Y (to be prepared separately for each Building/Wing of the Project)

Sr. No	Tasks/Activity	Percentage of work done
1	Excavation	100%
2	1 number of Plinth	100%
3	0 number of Podiums	100/0
4	Stilt Floor	100%
5	6 number of Slabs of Super Structure	100%
6	Internal walls, Internal Plaster, Floorings within Flats/Premises, Doors and Windows to each of the Flat/Premises	100%
7	Sanitary Fittings within the Flat/Premises	100%
8	Staircases, Lifts Wells and Lobbies at each Floor level connecting Staircases and Lifts, Overhead and Underground Water Tanks	100%
9	The external plumbing and external plaster, elevation, completion of terraces with waterproofing of the Building/Wing	100%
10	Installation of lifts, water pumps, Fire Fighting Fittings and Equipment as per CFO NOC, Electrical fittings to Common Areas, electro, mechanical equipment, compliance to conditions of environment/CRZ NOC, Finishing to entrance lobby/s, plinth protection, paving of areas appurtenant to Building/Wing, Compound Wall and all other requirements as may be required to Obtain Occupation/Completion Certificate	100%

#### Building/Wing Number Z (to be prepared separately for each Building/Wing of the Project)

Sr. No	Tasks/Activity	Percentage of work done
1	Excavation	100%
2	1 number of Plinth	100%
3	0 number of Podiums	10070
4	Stilt Floor	100%
5	6 number of Slabs of Super Structure	100%
6	Internal walls, Internal Plaster, Floorings within Flats/Premises, Doors and Windows to each of the Flat/Premises	100%
7	Sanitary Fittings within the Flat/Premises	100%
8	Staircases, Lifts Wells and Lobbies at each Floor level connecting Staircases and Lifts, Overhead and Underground Water Tanks	100%
9	The external plumbing and external plaster, elevation, completion of terraces with waterproofing of the Building/Wing	100%
10	Installation of lifts, water pumps, Fire Fighting Fittings and Equipment as per CFO NOC, Electrical fittings to Common Areas, electro, mechanical equipment, compliance to conditions of environment/CRZ NOC, Finishing to entrance lobby/s, plinth protection, paving of areas appurtenant to Building/Wing, Compound Wall and all other requirements as may be required to Obtain Occupation/Completion Certificate	100%

 $\begin{tabular}{ll} \textbf{Table - B} \\ \textbf{Internal \& External Development Works in Respect of the entire Registered Phase} \\ \end{tabular}$ 

Sr. No	Common areas and Facilities Amenities	Proposed (Yes/No)	Percentage of work done	Remarks
1	Internal Roads & Footpaths	yes	100%	
2	Water Supply	yes	100%	
3	Sewerage (chamber, lines, Septic Tank, STP)	yes	85%	
4	Storm Water Drains	ves	85%	
5	Landscaping & Tree Planting	yes	80%	
6	Street Lighting	ves	100%	
7	Community Buildings	yes	100%	
8	Treatment and disposal of sewage and sullage water /STP	no		
9	Solid Waste Management & Disposal	no		
10	Water Conservation, Rain Water Harvesting, Percolating Well/Pit	no		
11	Energy Management	no		
12	Fire Protection and Fire Safety Requirements	yes	100%	
13	Electrical Meter Room, Sub-station, Receiving Station	yes	90%	
14	Others (Option to Add more)	( )	7076	

Yours Faithfully,

HARSH P. PANDYA
(ARCHITECT)

HARSH PANDYA & ASSOCIATES
218-19, 2nd Floor, Lakulesh Avenue,
Delux Square, Nizampura, Vadodara.
VMC Lic. No.:

Counsil of Architects (CoA) Registration valid till 31/12/2019.