

B-114, Ajinkyatara, Opp. P.L. Deshpande Garden, Sinhagad Road, Pune - 411030. M: 9881139546 email: vishwanathjagtap@yahoo.co.in Annexure A

FORM 1

(see Regulation 3)

ARCHITECT'S CERTIFICATE

(To be submitted at the time of Registration of Ongoing Project and for withdrawal of Money from Designated Account)

Date: 12/02/2025

To, M/S. Unicorn Homes Gat No. 49, Shirsawadi Tal. Haveli Dist. Pune 412216

Subject: Certificate of Percentage of Completion of Construction Work of Sai Sankul having MahaRERA Registration Number P52100011321 being developed by Unicorn Homes.

Sir,

I/ We have undertaken assignment as Architect /Licensed Surveyor of certifying Percentage of Completion of Construction Work of Project Named Sai Sankul having MahaRERA Registration Number P52100011321, being developed by Unicorn Homes.

Based on Site Inspection, with respect to Layout/ each of the Building Wing of the aforesaid Real Estate Project. I certify that as on the date of this certificate, the Percentage of Work done for each of the building/Wing of the Real Estate Project under MahaRERA is as per Table A herein below. The percentage of the work executed with respect to each of the activity of the entire phase is detailed in Table B.

TABLE-A

Layout/Building/Wing Number (to be prepared separately for each Layout /Building/Wing of the Project)

Building A

| Sr. No. (1) | Tasks/Activity (2) | Percentage of Actual Work Done (As on date of the Certificate) (3) |
|----------------|--------------------|--|
| 1 | Excavation | 100 % |
| 2 | Basements (if any) | * |
| 3 | Podiums (if any) | - |
| 4 | Plinth | 100 % |
| 5 | Stilt Floor | 100 % |



| 6 | Slabs of Super Structure | 100 % |
|----|--|-------|
| 7 | Internal walls, Internal Plaster, Floorings, Doors and windows within Flats/Premises | 100 % |
| 8 | Sanitary Fittings within the Flat/Premises | 100 % |
| 9 | Staircases. Lifts Wells and Lobbies at each Floor level Overhead and Underground Water Tanks | 100 % |
| 10 | External plumbing and external plaster, elevation, completion of terraces with waterproofing of the Building Wing. | 100 % |
| 11 | Installation of Lifts, water pumps, Fire Fighting Fittings and Equipment as per CFO NOC, Electrical fittings, mechanical equipment, compliance to conditions of environment/CRZ NOC, Finishing to entrance lobby/s. plinth protection, paving of areas appurtenant to Building/Wing, Compound Wall and all other requirements as may be required to complete project as per specifications in agreement of Sale. Any other activities. | 90 % |

Building B

| Sr. No. (1) | Tasks/Activity (2) | Percentage of Actual Work Done (As on date of the Certificate) |
|----------------|--|--|
| | and the first of t | (3) |
| 1 | Excavation | 100 % |
| 2 | Basements (if any) | · 1 |
| 3 | Podiums (if any) | - 1200 |
| 4 | Plinth | 100 % |
| 5 | Stilt Floor | 100 % |
| 6 | Slabs of Super Structure | 100 % |
| 7 | Internal walls, Internal Plaster, Floorings, Doors and windows within Flats/Premises | 100 % |
| 8 | Sanitary Fittings within the Flat/Premises | 100 % |
| 9 | Staircases. Lifts Wells and Lobbies at each Floor level Overhead and Underground Water Tanks | 100 % |
| 10 | External plumbing and external plaster, elevation, completion of terraces with waterproofing of the Building Wing. | 100 % |
| 11 | Installation of Lifts, water pumps, Fire Fighting Fittings and Equipment as per CFO NOC, Electrical fittings, mechanical equipment, compliance to conditions of environment/CRZ NOC, Finishing to entrance lobby/s. plinth protection, paving of areas appurtenant to Building/Wing, Compound Wall and all other requirements as may be required to complete project as per specifications in agreement of Sale. Any other activities. | 90 % |



Building C

| Sr. No. (1) | Tasks/Activity (2) | Percentage of Actual Work Done (As on date of the Certificate) |
|----------------|--|--|
| | | (3) |
| 1 | Excavation | 100 % |
| 2 | Basements (if any) | -n en- |
| 3 | Podiums (if any) | - |
| 4 | Plinth | 100 % |
| 5 | Stilt Floor | 100 % |
| 6 | Slabs of Super Structure | 100 % |
| 7 | Internal walls, Internal Plaster, Floorings, Doors and windows within Flats/Premises | 100 % |
| 8 | Sanitary Fittings within the Flat/Premises | 100 % |
| 9 | Staircases. Lifts Wells and Lobbies at each Floor level Overhead and Underground Water Tanks | 100 % |
| 10 | External plumbing and external plaster, elevation, completion of terraces with waterproofing of the Building Wing. | 100 % |
| 11 | Installation of Lifts, water pumps, Fire Fighting Fittings and Equipment as per CFO NOC, Electrical fittings, mechanical equipment, compliance to conditions of environment/CRZ NOC, Finishing to entrance lobby/s. plinth protection, paving of areas appurtenant to Building/Wing, Compound Wall and all other requirements as may be required to complete project as per specifications in agreement of Sale. Any other activities. | 90 % |

Building D

| Sr. No. (1) | Tasks/Activity (2) | Percentage of Actual Work Done (As on date of the Certificate) (3) |
|----------------|--|--|
| 1 | Excavation | 100 % |
| 2 | Basements (if any) | |
| 3 | Podiums (if any) | 5 |
| 4 | Plinth | 100 % |
| 5 | Stilt Floor | 100 % |
| 6 | Slabs of Super Structure | 100 % |
| 7 | Internal walls, Internal Plaster, Floorings, Doors and windows within Flats/Premises | 100 % |



| 8 | Sanitary Fittings within the Flat/Premises | 100 % |
|----|--|-------|
| 9 | Staircases. Lifts Wells and Lobbies at each Floor level Overhead and Underground Water Tanks | 100 % |
| 10 | External plumbing and external plaster, elevation, completion of terraces with waterproofing of the Building Wing. | 100 % |
| 11 | Installation of Lifts, water pumps, Fire Fighting Fittings and Equipment as per CFO NOC, Electrical fittings, mechanical equipment, compliance to conditions of environment/CRZ NOC, Finishing to entrance lobby/s. plinth protection, paving of areas appurtenant to Building/Wing, Compound Wall and all other requirements as may be required to complete project as per specifications in agreement of Sale. Any other activities. | 90 % |

Building E

| Sr. No. (1) | Tasks/Activity (2) | Percentage of Actual Work Done (As on date of the Certificate) (3) |
|----------------|--|--|
| | Excavation | 100 % |
| 1 | Excavation | |
| 2 | Basements (if any) | v [†] |
| 3 | Podiums (if any) | • |
| 4 | Plinth | 100 % |
| 5 | Stilt Floor | 100 % |
| 6 | Slabs of Super Structure | 100 % |
| 7 | Internal walls, Internal Plaster, Floorings, Doors and windows within Flats/Premises | 100 % |
| 8 | Sanitary Fittings within the Flat/Premises | 100 % |
| 9 | Staircases. Lifts Wells and Lobbies at each Floor level Overhead and Underground Water Tanks | 100 % |
| 10 | External plumbing and external plaster, elevation, completion of terraces with waterproofing of the Building Wing. | 100 % |
| 11 | Installation of Lifts, water pumps, Fire Fighting Fittings and Equipment as per CFO NOC, Electrical fittings, mechanical equipment, compliance to conditions of environment/CRZ NOC, Finishing to entrance lobby/s. plinth protection, paving of areas appurtenant to Building/Wing, Compound Wall and all other requirements as may be required to complete project as per specifications in agreement of Sale, Any other activities. | 100 % |



Building F

| r. No. 1) | Tasks/Activity (2) | Percentage of Actual Work Done (As on date of the Certificate) |
|--------------|--|--|
| | | (3) |
| L | Excavation | 100 % |
| 2 | Basements (if any) | - |
| 3 | Podiums (if any) | • 14, |
| 4 | Plinth | 100 % |
| 5 | Stilt Floor | 100 % |
| 6 | Slabs of Super Structure | 100 % |
| 7 | Internal walls, Internal Plaster, Floorings, Doors and windows within Flats/Premises | 100 % |
| 8 | Sanitary Fittings within the Flat/Premises | 100 % |
| 9 . | Staircases. Lifts Wells and Lobbies at each Floor level Overhead and Underground Water Tanks | 100 % |
| 10 | External plumbing and external plaster, elevation, completion of terraces with waterproofing of the Building Wing. | 100 % |
| 11 | Installation of Lifts, water pumps, Fire Fighting Fittings and Equipment as per CFO NOC, Electrical fittings, mechanical equipment, compliance to conditions of environment/CRZ NOC, Finishing to entrance lobby/s. plinth protection, paving of areas appurtenant to Building/Wing, Compound Wall and all other requirements as may be required to complete project as per specifications in agreement of Sale. Any other activities. | 100 % |

Building G

| Sr. No. (1) | Tasks/Activity (2) | Percentage of Actual Work Done (As on date of the Certificate) |
|----------------|--|--|
| | | (3) |
| 1 | Excavation | 100 % |
| 2 | Basements (if any) | - v · · |
| 3 | Podiums (if any) | E . |
| | Plinth | 100 % |
| <u>4</u> 5 | Stilt Floor | 100 % |
| (360) | Slabs of Super Structure | 100 % |
| 7 | Internal walls, Internal Plaster, Floorings, Doors and windows within Flats/Premises | 100 % |

| 8 | Sanitary Fittings within the Flat/Premises | |
|----|--|-------|
| 9 | Staircases, Lifts Wells and Latti | 100 % |
| | Staircases. Lifts Wells and Lobbies at each Floor level Overhead and Underground Water Tanks | 100 % |
| 10 | External plumbing and external plaster, elevation, completion of terraces with waterproofing of the Building Wing. | 100 % |
| 11 | Installation of Lifts, water pumps, Fire Fighting Fittings and Equipment as per CFO NOC, Electrical fittings, mechanical equipment, compliance to conditions of environment/CRZ NOC, Finishing to entrance lobby/s. plinth protection, paving of areas appurtenant to Building/Wing, Compound Wall and all other requirements as may be required to complete project as per specifications in agreement of Sale. Any other activities. | 90 % |

Building H

| Tasks/Activity | Percentage of Actual Work Done (As on date of the |
|--|---|
| (2) | Certificate) |
| - The versa of the street of t | (2) |
| to add the same of | (3) |
| Excavation | 100 % |
| Basements (if any) | - |
| Podiums (if any) | • |
| Plinth | 50 % |
| Stilt Floor | 0 % |
| Slabs of Super Structure | 0 % |
| Internal walls, Internal Plaster, Floorings, Doors and | 0 % |
| | 0 % |
| Staircases. Lifts Wells and Lobbies at each Floor level | 0 % |
| External plumbing and external plaster, elevation, completion of terraces with waterproofing of the Building Wing. | 0 % |
| Installation of Lifts, water pumps, Fire Fighting Fittings and Equipment as per CFO NOC, Electrical fittings, | 0 % |
| environment/CRZ NOC, Finishing to entrance lobby/s. plinth protection, paving of areas appurtenant to | |
| requirements as may be required to complete project as per specifications in agreement of Sale. Any other | |
| | Excavation Basements (if any) Podiums (if any) Plinth Stilt Floor Slabs of Super Structure Internal walls, Internal Plaster, Floorings, Doors and windows within Flats/Premises Sanitary Fittings within the Flat/Premises Staircases. Lifts Wells and Lobbies at each Floor level Overhead and Underground Water Tanks External plumbing and external plaster, elevation, completion of terraces with waterproofing of the Building Wing. Installation of Lifts, water pumps, Fire Fighting Fittings and Equipment as per CFO NOC, Electrical fittings, mechanical equipment, compliance to conditions of environment/CRZ NOC, Finishing to entrance lobby/s. plinth protection, paving of areas appurtenant to Building/Wing, Compound Wall and all other requirements as may be required to complete project |



Building I

| r. No. | Tasks/Activity | T |
|--------|--|---|
| L) | - The state of the | Percentage of Actual Work |
| 77 | (2) | Done (As on date of the Certificate) |
| 411 | | (3) |
| | Excavation | 100 % |
| 2 | Basements (if any) | - |
| 3 | Podiums (if any) | |
| 4 | Plinth | 50 % |
| 5 | Stilt Floor | 0 % |
| 6 | Slabs of Super Structure | 0 % |
| 7 | Internal walls, Internal Plaster, Floorings, Doors and windows within Flats/Premises | 0 % |
| 8 | Sanitary Fittings within the Flat/Premises | 0 % |
| 9 | Staircases. Lifts Wells and Lobbies at each Floor level Overhead and Underground Water Tanks | 0 % |
| 10 | External plumbing and external plaster, elevation, completion of terraces with waterproofing of the Building Wing. | 0 % |
| 11 | Installation of Lifts, water pumps, Fire Fighting Fittings and Equipment as per CFO NOC, Electrical fittings, mechanical equipment, compliance to conditions of environment/CRZ NOC, Finishing to entrance lobby/s. plinth protection, paving of areas appurtenant to Building/Wing, Compound Wall and all other requirements as may be required to complete project as per specifications in agreement of Sale. Any other activities. | 0 % |

Building j

| Sr. No. (1) | Tasks/Activity (2) | Percentage of Actual Work Done (As on date of the Certificate) | |
|----------------|--|--|--|
| | | (3) | |
| 1 | Excavation | 100 % | |
| 2 | Basements (if any) | - | |
| 3 | Podiums (if any) | - | |
| 4 | Plinth | 50 % | |
| 5 | Stilt Floor | 0 % | |
| 6 | Slabs of Super Structure | 0 % | |
| 7 | Internal walls, Internal Plaster, Floorings, Doors and windows within Flats/Premises | 0 % | |

| 8 | Sanitary Fittings within the Flat/Premises | |
|----|--|-----|
| 9 | Staircases Lifts Wells and Little | 0 % |
| | Staircases. Lifts Wells and Lobbies at each Floor level Overhead and Underground Water Tanks | 0 % |
| 10 | External plumbing and external plaster, elevation, | U |
| | completion of terraces with waterproofing of the Building Wing. | 0 % |
| 11 | Installation of Lifts, water pumps, Fire Fighting Fittings and Equipment as per CFO NOC, Electrical fittings, mechanical equipment, compliance to conditions of environment/CRZ NOC, Finishing to entrance lobby/s. plinth protection, paving of areas appurtenant to Building/Wing, Compound Wall and all other requirements as may be required to complete project as per specifications in agreement of Sale. Any other activities. | 0 % |

TABLE-B

Common Areas (Internal and External Development Works) in respect of the Registered Phase / Project Number

| Sr. No. (1) | Common areas and Facilities (2) | Proposed (Yes/No) (3) | Percentage of Actual Work Done (As on date of the Certificate) (4) | Details (5) |
|----------------|---|-----------------------------|--|--|
| 1 | Internal Roads & Footpaths | Yes | 100 % | |
| 2 | Water Supply | Yes | 100 % | Borewell+ under ground & overhead tanks |
| 3 | Sewerage (Chamber, lines, Septic Tank, STP). | Yes | 75 % | Chamber, lines, Septic tank 100 % completed. STP installation pending. |
| 4 | Storm Water Drains | No | 1 1 2 | |
| 5 | Landscaping & Tree Planting | Yes | 100 % | |
| 6 | Street Lighting | Yes | 100 % | Solar panel street |
| 7 | Community Buildings | Yes | 0% | |
| 8 | Treatment and disposal of sewage and sullage water. | No | | |
| 9 | Solid Waste management & Disposal | Yes | 100 % | |
| 10 | Water conservation/ Rain | Yes | 100 % | |



| | water harvesting | | | |
|----|---|-----|-------|--------------------------------------|
| 11 | Energy management | Yes | 100 % | + |
| 12 | Fire protection and fire safety requirements | No | | Building height less than 15 Mtr. |
| 13 | Electrical meter room, substation, receiving station. | Yes | 100 % | |
| 14 | Others (Option to Add more). | - | - | |

REG. No. CAI96/19608

Yours Faithfully.

Signature & Name

MR. VISHWANATH JAGTAP

Architect

(License No. CA/96/19608

Agreed and Accepted by:

M/s. Unicorn Homes
Signature of Promoter:

Name: Mr. Mandar Mahendra Pawar

Date: 12/02/2025