B. ARCH., M. TECH-IIT-DELHI AIIA, AMIE, MICI, FIV, MACI.

ARCHITECT STRUCTURAL ENGINEER CONSTRUCTION MANAGEMENT CONSULTANT APPROVED VALUER SOIL & FOUNDATION EXPERT REPAIR & REHABILITATION EXPERT

BHAVESH PATEL

B. E. (CIVIL) M.E., SOIL & FOUNDATION-MUMBAI, MICI, MIGS, MACI.

Office: 3, Ground Floor, 'Tapasya', Behind Hamara Bazar, 60 Feet Road, Bhayandar (West) - 401 101. • Tel.: 2819 2619

Office: A/104, Rajeshri Accord, Telly Gulli Cross Lane, Near Rly. Station, Andheri (East), Mumbai - 400 069. 7 : 6520 2203

Ref. No.:

FORM 1

Date: 24(7/2017

[see Regulation 3]

ARCHITECT'S CERTIFICATE

(To be submitted at the time of Registration of Ongoing Project and for withdrawal of Money from Designated Account)

To,

M/S. H. K. Constructions,

Bhayandar, Taluka & Dist - Thane.

Subject: Certificate of Percentage of Completion of Construction Work of Building called Yashodeep Co.op Hsg. Soc. Ltd. [MahaRERA Registration Number] situated on the Plot bearing old S. No.- 17, New S. No.- 355, H. No.- 1B (C.T.S. No.- 1551 Part, Village – Bhayandar, Taluka – Thane demarcated by its boundaries (latitude 19.3105 N and longitude 72.8540 E of the end points) Exiting Road to the North, Grasy Apt. to the South, Road to the East, Hanuman Mandir to the West, of Division – Village – Bhayandar, Taluka – Thane, District – Thane, PIN – 401101 admeasuring 472 sq.mts. area being developed by M/S – H. K. Constructions.

Sir.

I, Bharatkumar P. Patel have undertaken assignment as Architect of certifying Percentage of Completion of Construction Work of the "Yashodeep Co.op Hsg. Soc. Ltd." Building situated on the plot bearing old S. No.- 17, New S. No.- 355, H. No.- 1B (C.T.S. No.- 1551 Part, Village – Bhayandar, Taluka – Thane, PIN – 401101 admeasuring 472 sq.mts. area being developed by M/S – H. K. Constructions.

C.M. amerika Egiri († 5.

A, AMIE, MICI, FIV, MACI.

ARCHITECT STRUCTURAL ENGINEER CONSTRUCTION MANAGEMENT CONSULTANT APPROVED VALUER SOIL & FOUNDATION EXPERT REPAIR & REHABILITATION EXPERT

BHAVESH PATEL

B. E. (CIVIL)
M.E., SOIL & FOUNDATION-MUMBAI,
MICI, MIGS, MACI.

Office: 3, Ground Floor, 'Tapasya', Behind Hamara Bazar, 60 Feet Road, Bhayandar (West) - 401 101. • Tel.: 2819 2619

Office: A/104, Rajeshri Accord, Telly Gulli Cross Lane, Near Rly. Station, Andheri (East), Mumbai - 400 069. 🙃: 6520 2203

Ref. No. :		Date: 24/7/201			
	그 생물이 바꾸었는 사람들이 그렇게 되었다.				
	1. Following technical professionals are appointed by Own	ner / Promoter :-			
	i) Shri Bharatkumar P. Patel as Architect				
	ii) Shri. K. C. Shah as Structural Consultant				
	iii) M/s / Shri / Smt as MEP Consultant				
	iv) M/s / Shri / Smt as Site Supervisor	9 . 3			
	Based on Site Inspection, with respect to each of the Building / Wing of the				
	aforesaid Real Estate Project, I certify that as on the date of				
	Percentage of Work done for each of the building / wing of the Real Estate Project as				
	registered vide number under MahaRERA is as per table A herein below.				
	The percentage of the work executed with respect to each of the activity of the entire				
	phase is detailed in Table B.				
	phase is detailed in Table B.				
	phase is detailed in Table B. TABALE – A				
	TABALE – A	be prepared separately for			
	TABALE – A Building called "Yashodeep Co.op Hsg. Soc. Ltd." (to	be prepared separately for			
	TABALE – A Building called "Yashodeep Co.op Hsg. Soc. Ltd." (to each Building / Wing of the Project)				
	TABALE – A Building called "Yashodeep Co.op Hsg. Soc. Ltd." (to each Building / Wing of the Project) Sr. No. Tasks / Activity	be prepared separately for Percentage of work done (3)			
	TABALE – A Building called "Yashodeep Co.op Hsg. Soc. Ltd." (to each Building / Wing of the Project) Sr. No. Tasks / Activity (1) (2)	Percentage of work done			
	TABALE – A Building called "Yashodeep Co.op Hsg. Soc. Ltd." (to each Building / Wing of the Project) Sr. No. Tasks / Activity (1) (2)	Percentage of work done (3)			
	TABALE – A Building called "Yashodeep Co.op Hsg. Soc. Ltd." (to each Building / Wing of the Project) Sr. No. Tasks / Activity (1) Excavation & Piling	Percentage of work done (3) 100 %			
	TABALE – A Building called "Yashodeep Co.op Hsg. Soc. Ltd." (to each Building / Wing of the Project) Sr. No. Tasks / Activity (1) (2)	Percentage of work done (3)			
	TABALE – A Building called "Yashodeep Co.op Hsg. Soc. Ltd." (to each Building / Wing of the Project) Sr. No. Tasks / Activity (1) Excavation & Piling	Percentage of work done (3) 100 %			
	TABALE – A Building called "Yashodeep Co.op Hsg. Soc. Ltd." (to each Building / Wing of the Project) Sr. No. Tasks / Activity (1) Excavation & Piling 1. number of Basement and Plinth	Percentage of work done (3) 100 %			
	TABALE – A Building called "Yashodeep Co.op Hsg. Soc. Ltd." (to each Building / Wing of the Project) Sr. No. Tasks / Activity (1) Excavation & Piling 1. number of Basement and Plinth	Percentage of work done (3) 100 %			
	TABALE – A Building called "Yashodeep Co.op Hsg. Soc. Ltd." (to each Building / Wing of the Project) Sr. No. Tasks / Activity (1) Excavation & Piling 1. number of Basement and Plinth	Percentage of work done (3) 100 %			

ARCH., M. TECH-IIT-DELHI JIA, AMIE, MICI, FIV, MACI.

ARCHITECT STRUCTURAL ENGINEER CONSTRUCTION MANAGEMENT CONSULTANT APPROVED VALUER SOIL & FOUNDATION EXPERT REPAIR & REHABILITATION EXPERT

BHAVESH PATEL

B. E. (CIVIL)
M.E., SOIL & FOUNDATION-MUMBAI,
MICI, MIGS, MACI.

Office: 3, Ground Floor, 'Tapasya', Behind Hamara Bazar, 60 Feet Road, Bhayandar (West) - 401 101. • Tel.: 2819 2619

Office: A/104, Rajeshri Accord, Telly Gulli Cross Lane, Near Rly. Station, Andheri (East), Mumbai - 400 069. 7 : 6520 2203

Ref. No. :			Date :	24/7/2017
	3.	number of Podium	Not Applicable	
	4.	Stilt Floor	0 %	
	5.	12 number of Slabs of Super Structure	0 %	
	6.	Internal Walls, Internal Plaster, Floorings	0 %	
		within Flats / Premises, Doors and Windows	3 4 3	
		to each of the Flat / Premises.		
	7.	Sanitary Fittings within the Flat / Premises,	0 %	
		Electrical Fittings within the Flat / Premises.		
	8.	Staircase, Lifts Wells and Lobbies at each	0 %	
		Floor level connecting Staircase and Lifts,		
		Overhead and Underground Water Tanks.		
	9.	The external plumbing and external plaster,	0 %	
		elevation, completion of terraces with		
		waterproofing of the Building / Wing.		
	10.	Installation of lifts, water pumps, Fire Fighting	0 %	
		Fittings and Equipment as per CFO NOC,		
		Electrical fittings to Common Areas, electro,		
		mechanical equipment, Compliance to conditions		
		of environment / CRZ NOC, Finishing to entrance		
		lobby/s, plinth protection, paving of areas		
		appurtenant to Building / Wing, Compound wall		
	4	and all other requirements as may be required to	N.	
		obtain Occupation / Completion Certificate.		
		man si visilini. Pilik Pilik Duri (1955)		

La sell de la litte, war a die 3 a. Libè. Fighte des la circa marcas de CFO NGC

Heorical Ethnis of Gonzaot Abert Cec

mechanica sociament Compliant, n co.

er senjedemister (der 2000) er er er

ARCH., M. TECH-IIT-DELHI JIA, AMIE, MICI, FIV, MACI.

ARCHITECT STRUCTURAL ENGINEER CONSTRUCTION MANAGEMENT CONSULTANT APPROVED VALUER SOIL & FOUNDATION EXPERT REPAIR & REHABILITATION EXPERT

BHAVESH PATEL

B. E. (CIVIL) M.E., SOIL & FOUNDATION-MUMBAI, MICI, MIGS, MACI.

Office: 3, Ground Floor, 'Tapasya', Behind Hamara Bazar, 60 Feet Road, Bhayandar (West) - 401 101. • Tel.: 2819 2619

Office: A/104, Rajeshri Accord, Telly Gulli Cross Lane, Near Rly. Station, Andheri (East), Mumbai - 400 069. 7 : 6520 2203

Ref. No.:

Date: 24/7/2017

	9.	TABLE – B		
Intern	al and External Developmer	nt Works in respec	t of the entire Registe	red Phase.
S. No.	Common areas	Proposed	Percentage of	Details
	and Facilities,	(Yes/No)	Work done	
	Amenities		858	
(1)	(2)	(3)	(4)	(5)
l.	Internal Roads &	No	Not Applicable	
	Foothpaths.		88	
2.	Water Supply	Yes	0.%	
3.	Sewarage (chamber,	Yes	0 %	
	lines, Septic Tank, STP).	and the second second	~ p	
4.	Storm Water Drains	Yes	0 %	
5.	Landscaping & Tree	Yes	- 0 %	
	Planting,			
6.	Street Lighting	No	Not Applicable	
7.	Community Buildings	No	Not Applicable	
8.	Treatment and disposal	No	Not Applicable	
	of sewage and sullage			
	water.	· Virgini		
9.	Solid Waste management	t Yes	0 %	
	& Disposal.			
10.	Water conservation, Rair	ı <u>Ye</u> s	0 %	
	Water conservation, Rair water harvesting.	Y da	69.	
	Tist in	4	. 5×.	
		· 186		

ARCH., M. TECH-IIT-DELHI
JIA, AMIE, MICI, FIV, MACI.

Ref. No.:

ARCHITECT STRUCTURAL ENGINEER CONSTRUCTION MANAGEMENT CONSULTANT APPROVED VALUER SOIL & FOUNDATION EXPERT REPAIR & REHABILITATION EXPERT

BHAVESH PATEL

B. E. (CIVIL)
M.E., SOIL & FOUNDATION-MUMBAI,
MICI, MIGS, MACI.

Date: 24/7/2017

Office: 3, Ground Floor, 'Tapasya', Behind Hamara Bazar, 60 Feet Road, Bhayandar (West) - 401 101. • Tel.: 2819 2619

Office: A/104, Rajeshri Accord, Telly Gulli Cross Lane, Near Rly. Station, Andheri (East), Mumbai - 400 069. 7: 6520 2203

11.	Energy management	Yes	0 %	
12.	Fire protection and fire	Yes	0 %	
	safety requirements			
13.	Electrical meter room,	Yes	0 %	
	sub-station, receiving station.			
14.	Others (Option to Add more).	No	Not Applicable	

Yours Faithfully,

A sy Parel

Architect Bharatkumar P. Patel

(License No. CA/88/11407)

BHARATKUMAR PATH

B.ARCH, MITECH, LLT. (DELHI)

ARCHITECY

Ca/88/11407

CHARTERED ENGINEER

Alia 76839/4