

## FORM 1

## **ARCHITECT'S CERTIFICATE**

Date: 30<sup>th</sup> March 2019

To M/s. Paradigm Ambit Buildcon, 202, Roopmangal Building, G52. Corner of Main Avenue & 16<sup>th</sup> Road, Santacruz – West, Mumbai – 400 054

Subject:

Certificate of Percentage of Completion of Construction Work of Sale Building having Wing A, B, C & D of the Project situated on the Plot bearing FP NO - 383, TPS - III, Village - Borivali Shimpoli, Taluka - Borivali (W) / Final Plot no demarcated by its boundaries (Sale Building 1) Latitude – 19 13 30.9253 N Longitude 72 50 38.913" E 2) Latitude – 19°13 30.8241 N Longitude 72°50 38.913" E 3) Latitude – 19°13 29.4487 N Longitude 72°50 39.038" E 4) Latitude – 19° 13 29.609 N Longitude 72° 50 39.038" E) FP – 379, 380,381 & 382 to the North, 13.40m Wide DP Road to the South, FP - 384 to the East, 13.40M wide DP Road to the West of Division – Mumbai, Village – Borivali, Taluka - Borivali District – Mumbai Suburban District PIN admeasuring 7014.71 sq.mts. Area being developed by [M/s. Paradigm Ambit Buildcon.

Sir,

I / We **M/s. DOT Architects** have undertaken assignment as Architect of certifying Percentage of Completion of Construction Work of Sale Building having Wing A, B, C & D of the Project, situated on the Plot bearing FP NO - 383, TPS - III, Village - Borivili Shimpoli, Taluka - Borivali (W) / Final Plot no of Division – Mumbai, Village – Borivili, Taluka - Borivili District – Mumbai Suburban District, PIN – 400092, admeasuring **7014.71** sq.mts. area being developed by **[M/s. Paradigm Ambit Buildcon]** 

- 1. Following technical professionals are appointed by Owner / Promoter:-
  - I. M/s. DOT Architects as L.S. / Architect; M/s. DOT Architects
  - II. M/s. Gireesh M Rajadhyaksha as Structural Consultant
  - III. M/s. URJA BUILDING SERVICES CONSULTANTS PVT.LTD. as MEP Consultant
  - IV. Shri. Kamlesh Gurav as Site Supervisor

Based on Site Inspection, with respect to each of the Wings of the aforesaid Real Estate Project, I certify that as on the date of this certificate, the Percentage of Work done for Sale building having Wing A, B, C & D of the Real Estate Project to be registered under Maha RERA is as per table A herein below. The percentage of the work executed with respect to each of the activity of the entire phase is detailed in **Table B**.



Table A

Sr. No done	. Tasks /Activity	Percentage of work	
1	Excavation	100%	
2	R.C.C. Work 2 level sunken pit	100%	
3	R.C.C. 2 Level Podium	100%	
4	R.C.C. Work Stilt Floor	100%	
5	R.C.C. Work of Wing A & B (20 slabs), Wing C & D (20 Slabs)  100%		
6	Internal walls, Internal Plaster, 70% Floorings within Flats/ Premises, Doors and Windows to each of the Flat/ Premises		
7	Sanitary Fittings within the Flat/Premises, 40% Electrical Fittings within the Flat/ Premises		
8	Staircases, Lifts Wells and Lobbies at each 70%  Floor level connecting Staircases and Lifts, Overhead and Underground Water Tanks		
9	The external plumbing and external plaster, 80% elevation, completion of terraces with waterproofing of the Building/Wing,		
10	Installation of lifts, water pumps, Fire Fighting Fitting and Equipment as per CFO NOC, Electrical fittings to Common Areas, electro, mechanical equipment, Compliance to conditions of environment / CRZ NOC, Finishing to entrance lobby/s, plinth protection, paving of areas appurtenant to Building/Wing, Compound Wall and all other	ngs 30%	
	requirements as may be required to Obtain  Occupation / Completion Certificate		



**TABLE-B** 

S. No.	Common areas and Facilities, Amenities	Proposed (Yes/No)	Percentage of Work done	
1	Internal Roads & Footpaths	Yes	0%	
2	Water Supply	Yes	0%	
3	Sewerage (chamber, lines, Septic Tank , STP)	Yes	0%	
4	Storm Water Drains	Yes	0%	
5	Landscaping & Tree Planting	Yes	0%	
6	Street Lighting	Yes	0%	
7	Community Buildings	Yes	0%	
8	Treatment and disposal of sewage and sullage water	Yes	0%	
9	Solid Waste management & Disposal	Yes	0%	
10	Water conservation, Rain water harvesting	Yes	0%	
11	Energy management	Yes	0%	
12	Fire protection and fire safety requirements	Yes	0%	
13	Electrical meter room, sub-station, receiving station	Yes	0%	
14	Others ( Option to Add more)	Yes	0%	

Hence the Construction work of Sale Building has been completed upto 70 % of total work on date.

Thanking you,

Yours Faithfully,

M/s DOT Architects

Partner Wald