

To Aqura Builder and Developer Pvt Ltd Aqura Pride, S. No. 73/1, Canal Road, Vadgaon Budruk, Pune-411041

Sir,

I/We Jay Aeram have undertaken assignment as Architect /Licensed Surveyor of certifying percentage of Completion of Construction Work of the Building of the Project named as "AQURA PRIME", situated on the Plot bearing CTS 7737 & 7740, village Ramwadi, Vadgaon Sheri Taluka Haveli District Pune PIN-411041 having [MahaRERA No.............] developed by "AQURA BUILDERS AND DEVELOPERS PVT LTD".

Following technical professionals are appointed by Owner / Promoter:-

- i. M/s/Shri./Smt.Mr. Jay Aeram as L.S. /Architect:
- ii. M/s/Shri. /Smt. Mr Hansel Parekh as Structural Consultant
- iii. M/s/Shri. /Smt. Mr Swagat Yadav as MEP Consultant
- iv. M/s/Shri./Smt. Mr Vijay Bahadure as Site Supervisor

Based on Site Inspection, with respect to each of the Building/Wing of the aforesaid Real Estate Project, I certify that as on the date of this certificate, the Percentage of Work done for each of the building/Wing of the Real Estate Project which is yet to be registered under MahaRERA is as per table A herein below. The percentage of the work executed with respect to each of the activity of the entire phase is detailed in Table B.

CA-93/15811) **

Table A
Building Number A

Sr. No.	Tasks / Activity	Percentage of work done	
1.	Excavation	0%	
2.	number of Basement (s) and 1 Plinth &	0%	
3.	number of Podiums / Upper Parking	0%	
4.	Stilt Floor.	0%	
5.	number of Slabs of Super Structure	0%	
6.	Internal walls, Internal Plaster, Floorings within Flats/Premises, Doors and Windows to each of the Flat/Premises	0%	
7.	Sanitary Fittings within the Flat /Premises, Electrical Fittings within the Flat/Premises	0%	
8.	Staircases, Lifts Wells and Lobbies at each Floor level connecting Staircases and Lifts, Overhead and Underground Water Tanks	0%	
9.	The external plumbing and external plaster, elevation, completion of terraces with waterproofing of the Building/Wing.	0%	
10.	Installation of lifts, water pumps, Fire Fighting Fittings and Equipment as per CFO NOC, Electrical fittings to Common Areas, electro, mechanical equipment, Compliance to conditions of environment/CRZ NOC, Finishing to entrance lobby/s, Plinth protection, paving of areas appurtenant to Building/Wing, Compound Wall and other requirements as may be required to Obtain Occupation/Completion Certificate	0%	



TABLE-BInternal & External Development Works in Respect of the entire Registered Phase

S. No.	Common areas and Facilities, Amenities	Proposed (Yes/No)	Percentage of Work done	Details
1.	Internal Roads & Footpaths	NO 6	0%	WORK NOT STARTED
2.	Water Supply	YES	0%	WORK NOT STARTED
3.	Sewerage (Chamber, lines, Septic Tank,	YES	0%	WORK NOT STARTED
4.	Storm Water Drains	YES	0%	WORK NOT STARTED
5.	Landscaping & Tree Planning	NO	0%	WORK NOT STARTED
6.	Street Lighting	YES	0%	WORK NOT STARTED
7.	Community Buildings	NO	-	WORK NOT STARTED
8.	Treatment and disposal of sewage and sullage water	NO	-	WORK NOT STARTED
9.	Solid Waste management & Disposal	NO	Carbova <mark>qua C</mark>	WORK NOT STARTED
10.	Water Conservation, Ran water harvesting	YES	0%	WORK NOT STARTED
11.	Energy management	YES	0%	WORK NOT STARTED
12.	Fire protection and fire safety requirements	YES	0%	WORK NOT STARTED
13.	Electrical meter room, substation, receiving station	YES	0%	WORK NOT STARTED
14.	Others (Option to Add more)	NO		WORK NOT STARTED

Thanking You,

Regards

Ar.Jay Aeram (Reg No CA/93/15811)